

Technical Service Bulletin



91 Park assist plus: currently unavailable message displayed in the MMI while located in NY, VT or Puerto Rico

91 23 12 2066110/2 July 7, 2023. Supersedes Technical Service Bulletin Group 91 number 22-86 dated March 4, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2023		
A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron quattro, e-tron Sportback quattro, e-tron S quattro, Q7, SQ7, Q8, SQ8, and RS Q8	2023	All	Not Applicable
Q8 e-tron, and Q8 Sportback e-tron	2024		

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised title (Added Puerto Rico) Revised header (Added MY23/24 vehicles with park assist plus) Revised <i>Technical Background</i> (Added Puerto Rico)
1	03/04/2022	Initial publication



Customer states:

- The park assist plus system does not activate when pushing the park assist plus button.



Figure 1: Park assist plus button

- The message “Park assist plus: currently unavailable” is displayed on the MMI screen.



Figure 1: Park assist plus: currently unavailable message

Workshop findings:

- No relevant DTCs are stored.

Technical Background

Park assist plus is currently geofenced to be unavailable if the vehicle is physically located in one of the following states/territories:

- New York
- Vermont
- Puerto Rico

Production Solution

Not applicable.

Service

No repair is available at this time as the vehicle is operating as designed.

1. Do not perform any repairs. Any repairs for this concern may be denied.



2. Instruct the customer that this condition is normal.

Warranty

This TSB is informational only and not covered by any Audi warranty.

Additional Information

All parts and service references provided in this TSB (**2066110**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.