

Technical Service Bulletin (TSB)

Heated Windshield Inoperative

REFERENCE:	TSB: 23-050-23 GROUP 23 - Body	Date:	May 10, 2023	REVISION:	-
VEHICLES	2023 (JL) Jeep Wrangler This bulletin applies to vehicles built on or after February 23, 2023 (MDH 0223XX) and on or before March 24, 2023 (MDH 0324XX).			MARKET APPLICABILITY:	
AFFECTED:				⊠NA	□СН
				⊠EE	□IAP
				⊠SA	⊠MEA
CUSTOMER SYMPTOM:	Customers may comment on the followThe heated windshield is inoperation	•			
CAUSE:	Electrical connection button is not fully engaged onto the windshield.				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-133, date of issue May 10, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/ Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly connecting the heated windshield button to the windshield.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time	
23-30-50-9P	Heated Windshield But- ton Connection - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.	
23-30-50-9Q	Heated Windshield But- ton connection - Inspect and Repair (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.	
Failure Code ZZ		Service Action		

DIAGNOSIS:

- If a customer's VIN is listed in VIP or your RSU VIN list, perform the inspection.
- 1. Visually look at the windshield heated button being disconnected (Fig. 1) .



Fig. 1 Heated Windshield Button Is Disconnected

- 2. Is the heated windshield button disconnected?
 - YES>>> Proceed to Step 1 of the Repair Procedure.
 - NO>>> This bulletin has been completed. Use inspect LOP (23-30-50-9P) to close the active RSU. Normal diagnosis should be performed.

REPAIR PROCEDURE:

1. Connect the heated windshield button to the windshield.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.