

REFERENCE:	TSB: 19-003-23 REV. B GROUP 19 - Steering	Date:	May 12, 2023	REVISION:	19-003-23 REV. A
VEHICLES AFFECTED:	<p>2022 - 2023 (B1) Jeep Renegade This bulletin applies to vehicles built on or after May 07, 2022 (MDH 0507XX) and on or before **April 18, 2023 (MDH 0418XX)**.</p> <p>2022 - 2023 (M1) Jeep Compass This bulletin applies to vehicles built on or after July 27, 2022 (MDH 0727XX) and on or before **April 18, 2023 (MDH 0418XX)**.</p> <p>2023 (H1) Jeep Commander This bulletin applies to vehicles built on or after **January 06, 2023 (MDH 0106XX) and on or before April 18, 2023 (MDH 0418XX).**</p>	MARKET APPLICABILITY:			
CUSTOMER SYMPTOM:	Customers may experience the steering wheel is off-center.				
CAUSE:	Steering wheel centering.				

This bulletin supersedes Technical Service Bulletin (TSB) 19-003-23 REV. A, date of issue April 15, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include additional build dates, new Rapid Service Update (RSU) number and LOP.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) ****23-138, date of issue May 12, 2023****. All applicable SU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves re-centering the steering wheel.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
**02-00-99-9P	Set Up On Alignment Machine, Inspect Steering Wheel Centering. (2 - Skilled)	19- Steering	0.5 Hrs.
02-00-99-9Q	Set Up On Alignment Machine , Inspect Steering Wheel Centering, Perform Front Toe Adjustment. (2 - Skilled)	19- Steering	0.6 Hrs.**
Failure code	ZZ	Service Action	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

1. Set up vehicle on alignment machine. Is the steering wheel off-center?
 - YES>>>Proceed to [Step 1](#) of the Repair Procedure.
 - NO>>> This bulletin has been completed, use inspect LOP (02-00-99-9P) to close the active RSU.

REPAIR PROCEDURE:

1. Perform front toe adjustment. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 02 Front Suspension / Wheel Alignment / Standard Procedure> Front Wheel Alignment> Toe adjust.
2. Confirm steering wheel is centered.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.