

<b>REFERENCE:</b>	<b>TSB:</b> 08-079-23 REV. A <b>GROUP</b> 08 - Electrical	<b>Date:</b>	May 24, 2023	<b>REVISION:</b>	08-079-23
<b>VEHICLES AFFECTED:</b>	<p>2022 (DT) RAM 1500 Pickup                  2022 (DJ) RAM 2500 Pickup                  2022 (DD) RAM 3500 Cab Chassis                  2022 (D2) RAM 3500 Pickup                  2022 (DF) RAM 3500 10K LB. Cab Chassis                  2022 (DP) RAM 4500/5500 Cab Chassis                  2022 - 2023 (DS) RAM 1500 Pickup                  This bulletin applies to vehicles equipped with the following radio:</p> <ul style="list-style-type: none"> <li>Uconnect 5 W 8.4" Display (Sales Code UBD) and Global Telematics Box Module (Sales Code RDG).</li> </ul> <p>This bulletin applies to DS vehicles built on or before April 3, 2023 (MDH 0403XX).</p>			<b>MARKET APPLICABILITY:</b>	
<b>CUSTOMER SYMPTOM:</b>	<ul style="list-style-type: none"> <li>None available at this time.</li> </ul>				
<b>CAUSE:</b>	Radio Software				

**REPAIR SUMMARY:**

This bulletin supersedes Technical Service Bulletin (TSB) 08-079-23, date of issue April 4, 2023, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

**DISCUSSION:**

The FOTA campaign for this software update has been stopped until further notice.

**POLICY:**

Information Only

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*