

GPOP - Issue Review System

Part Number: 68588637A\$, 68588639A\$, 68588643A\$, 68588647A\$,
68598819A\$, 68611543A\$

Part Description: Occupant Restraint Controller

Issue For concern of DTC B2767-49 Left Impact Pressure Sensor-Internal Failure OR DTC
Description: B2768-49 Right Impact Pressure Sensor-Internal Failure, prior to replacement of any
components please contact FCA Redacted Content for further assistance. If no
response in 15 minutes, proceed with repair.