

Case Number: S2325000005 Rev. A

Release Date: May 2023

Symptom/Vehicle Issue: Customer's concern may include Mil Lamp On.

Customer Complaint/Technician Observation: Upon further investigation, there may be a DTC set in the Powertrain Control Module (PCM) for P219A-BANK 1 AIR-FUEL RATIO IMBALANCE.

Discussion: If the diagnostics do not lead to a clear root cause, please erase the DTC and return the vehicle to the customer. The setting of the DTC under certain conditions is under engineering investigation and replacement of hardware will not likely lead to a repair of the condition at this time.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.