



STAR ONLINE PUBLICATION



Case Number: S2308000053

Release Date: May 2023

Symptom/Vehicle Issue: Traffic Sign Recognition (TSR) Speed Displayed on the Cluster Does Not Match the Actual Speed Limit Sign

Customer Complaint/Technician Observation: Owner complaint, when using the TRS system the cluster displays a speed limit sign showing a different speed then the posted speed limit sign for the area; or at times the change is slow to update to the correctly posted speed limit sign. Technician observed the same on certain roads.

Discussion: Do not replace any parts for this concern, replacement parts will perform the same. Engineering is requesting the Half module software to be updated for this this concern. Updates are expected for a service release by the 2nd quarter 2023. Updates are to the Half module to ensure the newest software version available is installed and proxi aligned.



Incorrect speed
for NAFTA –
Displays
European speed
limit.

Correct

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found