



## STAR ONLINE PUBLICATION



**Case Number:** S2323000041

**Release Date:** May 2023

**Symptom/Vehicle Issue:** 3<sup>rd</sup> Row Manual Seat Will Not Fold Using Seat Back Release Handle.



**Discussion:** The 3<sup>rd</sup> row manual seat uses a cable system to release the seat from the upright position to the folded position. If the seat will not fold, inspect the release handle and the cables on the seat back (Fig 1). Release cable barrels should be engaged in the handle slots. Cables should not be slack and no visible kinks. Cable or handle replacement will be necessary if there is visible kinks or damage.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**



## STAR ONLINE PUBLICATION




Fig 1

3<sup>rd</sup> Row Seat Handle Pulled To Show Cables And Attachments.

Refer to StarParts 1115.01 Interior, 3<sup>rd</sup> Row Manual Folding Seat for replacement cable and handle part information. For repair information refer to Service Library 23 - Body / Seats, Third Row / CABLE, Seat Back Release / Removal and Installation.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**