

Tech Tip L-TT-0322-23

June 01, 2023

| Subject | | Market |
|---|-------------------------------|--------|
| MIL ON and Multiple DTC for MGR Communication | | USA |
| Codes | | |
| Service Category | Section | |
| Drivetrain | Hybrid Transmission/Transaxle | |
| Applicability | | |
| 23MY RX500h AWD | | |

APPLICABLE VEHICLES

2023 RX500H

CONDITION

Vehicle may exhibit one or all in combination of the following DTC U115687 or U11B900 or U11B987 or U11BF87 shortly after short pin installed during PDS/PDI.

RECOMMENDATIONS

If you have cleared the codes and the codes have returned with the vehicle odometer over 13 miles and has over 12hrs since short pin installed, please contact TAS. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on

09/01/2023 Rev2

© 2023, Lexus, a Division of Toyota Motor Sales, USA