

Hands-Free Access (SA Code 871) Only Opens/Closes Trunk Lid After Several Attempts

Topic number	LI80.61-P-076671
Version	1
Function group	80.61 - Keyless-Go/Keyless-Entry
Date	7/11/23
Validity	Model Series 254 with SA code 871 (Hands-Free Access)
Reason for change	

Complaint

The trunk lid only opens/closes successfully after several attempts.

Cause

Coding in the Hands-Free Access control unit (N38).

Remedy

Perform SCN coding in Hands-Free Access control unit (N38).

Symptoms				
Overall vehicle > Safety and locking system > Keyless go > Function > Vehicle does not open				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			8000G	Fault type 90