

Technical product information

Topic	DTC B101C29 and/or DTC B101D29 evident within the airbag control unit (J234)
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2071047/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0015 - Airbag	B101C29: Driver seat belt switch implausible signal		Intermittent
0015 - Airbag	B101D29: Front passenger side safety belt switch implausible signal		Intermittent
0015 - Airbag	B101C29: Driver seat belt switch implausible signal		static
0015 - Airbag	B101D29: Front passenger side safety belt switch implausible signal		static

New customer code

Object of complaint	Complaint type	Position
occupant protection, pedestrian protection -> airbag	component / consumables	
occupant protection, pedestrian protection -> seat belts, 1st row	component / consumables	

Vehicle data

Bentayga Series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2021	E		*	*	*
4V1*	2022	E		*	*	*
4V1*	2023	E		*	*	*
ZV1*	2023	E		*	*	*

Documents

Document name
master.xml

DTC B101C29 and/or DTC B101D29 evident within the airbag control unit (J234)

Customer statement / workshop findings

One or a combination of the following DTC's is evident within the airbag control unit (J234)

B101C29: Driver seat belt switch implausible signal

And/or

B101D29: Front passenger side safety belt switch implausible signal

Technical background

Refer to the Measure section of this TPI

Production change

-

Measure

In the event that one or both DTC's are evident the operative must conduct the following:

- Raise a technical DISS query - Ensure a current ODIS log is attached to the technical DISS query
- Await feedback from Product support before conducting any further work or diagnosis

NOTICE

NOTE TO PRODUCT SUPPORT ON RECEIPT OF A QUALIFYING DISS QUERY

- Please second level the query to the Electrical Senior Engineer - Do Not respond until a response has been received from the Electrical Senior Engineer