

Dull ticking or thumping in the area of the engine/two-mass flywheel/transmission

Topic number	LI01.00-P-076642
Version	1
Function group	01.00 - General
Date	6/29/23
Validity	SL43 (232450), C43 (206087, 206287)
Reason for change	

Complaint

Dull thumping noise or ticking noise under the vehicle in the area of the engine/two-mass flywheel/transmission.
Is also faintly audible in the vehicle interior.

Attachments	
File	Description
seitlich.mp4	Noise audible from the side
Innenraum.mp4	Noise audible in the vehicle interior (quiet)
Unterboden.MOV	Noise under the vehicle

Cause

Under analysis

Remedy

Create a TIPS case

Do not replace any parts

Symptoms
Power generation > Engine noise > Noise
Power transmission > Automatic transmission > Noises > Noise

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note