

PANORAMIC ROOF OPENING PANEL AND/OR ROOF BLIND ONE TOUCH INOPERATIVE

Customer Voice:

- The roof opening panel blind will not automatically open when the roof opening panel is requested to the tilt or open positions.

Technical Description:

- The roof opening blind motors may have been built with incorrect software.

Status:

- **SSM 76030** has been published to address this concern.
- Both roof opening panel blind motors (LR157828) will require replacement.

Range Rover
• 23MY Velar

