

---

<b>Reference</b>	SSM76030
<b>Models</b>	Range Rover Velar / L560
<b>Title</b>	L560 23MY roof opening and blind panel incorrect operation
<b>Category</b>	Body
<b>Last modified</b>	10-Jul-2023 00:00:00
<b>Symptom</b>	105000 Roof Options

---

**Content**      **Issue:**  
Roof opening panel blind will not automatically open when the roof opening panel is requested to be tilted or opened.

**Cause:**  
Incorrect software installed in the roof opening blind motors.

**Action:**  
Replace both Roof opening panel blind motors following TOPIx:501-17 - Roof opening panel - Roof opening panel blind motor. Service part number LR157828 x 2.

anBhdHRicnM7MjAyMy0wOC0wMlQxMjczMzo0OC45MjFhOzEzNi4yMjYyNTAuMTEzOw==