

WPF9 - Reviewing Owner's Manual and Replacing it if Necessary (Workshop Campaign)

Model Line: **Taycan (Y1A / Y1B / Y1C)**

Model Year: **As of 2020 up to 2022**

Concerns: **Owner's Manual**

Cause: **The affected vehicles were potentially not delivered with the latest Owner's Manual for this vehicle type due to country-dependent supply bottlenecks of the printed Owner's Manual.**
As a result, the Owner's Manual supplied with the vehicle may not be up-to-date.

Action: Review Owner's Manual and replace it if necessary.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required parts (MY 2020 - 2021) - only if needed



Information

The required Owner's Manual must be determined according to model year and language version from the table below.

Parts Info:

Order No.	Designation - Language	Ordering via
		Polaris (PPL)
WKDY1A04B2122	Owner's Manual - English US	■

Required parts (MY 2022) - only if needed:



Information

The required Owner's Manual must be determined according to model year and language version from the table below.

Parts Info:

Order No.	Designation - Language	Ordering via
		Polaris (PPL)
WKDY1A02B2122	Owner's Manual - English US	■

Review Owner's Manual and replace if necessary

Work Procedure: 1 Check that the Owner's Manual in the vehicle is up-to-date.

1.1 Compare the order number of the Owner's Manual, taking into account the model year-dependent distinction.

1.2 If the Owner's Manual does not comply with the latest version: Replace Owner's Manual.

2 Enter the campaign in the Warranty and Maintenance logbook.

Warranty processing**Information**

The specified labor times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent rework. The labor times may differ from the labor times published in the Labor Operation List in PCSS.

Scope 1: **Reviewing Owner's Manual****Labor time:**

Reviewing Owner's Manual

Labor time: **10 TU**

⇒ Damage number WPF9 066 000 1

Scope 2: **Review Owner's Manual and replace****Labor time:**

Review Owner's Manual and replace

Labor time: **10 TU**

⇒ Damage number WPF9 66 000, repair code 2

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2023 Porsche Cars North America, Inc.