



Rosenbauer America Technical Service Bulletin TSB23001

Subject: The vehicle speed sensor fault code 241 is causing OEM speedometer inaccuracy on some Rosenbauer fire trucks with Cummins L9 Engines per Cummins TSB230127.

Problem: The speedometer may show a higher speed than what the truck is traveling at.

Applies To: Certain CM2450 L9 Cummins Engines with model years of 2021, 2022, 2023. Rosenbauer has identified possible candidates in the attached list of trucks.

Assistance Needed: Dealers to forward the Cummins Technical Service Bulletin to the list of customers in the attached file. Field questions and guide customers to resolve the issue. If known, submit an SRS ticket when resolved.

Resolution: If this problem occurs, contact your local authorized Cummins service provider for assistance in determining if your engine needs the revised ECM calibration code.

Note: This is a technical service bulletin and is not a recall.

Contact recalls@rosenbaueramerica.com with questions.

