

SSM 51847

2023 Corsair - 2.5L PHEV - Illuminated Powertrain Malfunction Indicator (Wrench) Lamp With Diagnostic Trouble Code (DTC) U1010 Stored In The SOBDMB

Some 2023 Corsair vehicles equipped with a 2.5L plug-in hybrid electric vehicle (PHEV) engine may exhibit an illuminated powertrain malfunction indicator (wrench) lamp with DTC U1010 stored in the secondary on-board diagnostic module-B (SOBDMB). This concern typically happens after a plug-in charging event. This condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that engineering is currently working on a solution for this condition that is expected in October 2023. Replacement or reprogramming of the SOBDMB is not recommended for this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.