



Bulletin No.: PIC6511
Published date: 07/12/2023

Preliminary Information

PIC6511 Diagnostic Tip - Unwanted Park Assist Indication


Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2023 - 2024	All	All	All	All

Involved Region or Country	North America
Condition	A customer may comment that the Park Assist will indicate an object detected intermittently from either the left or right front middle sensors.
Cause	Possible interference from front License Plate Frame.

Correction:

Example of Park Assist indicator.





1. Check for a License Plate Frame to be installed on the front License Plate similar to the picture above.
2. If a License Plate Frame is present, remove the frame and re-evaluate for the concern.
3. If the concern is no longer present, do not re-install the License Plate Frame.
4. If the concern is still present, refer to normal SI Diagnostics.

Warranty Information

Version History

Version	1
Modified	07/12/2023 - Created on.



© 2023 General Motors. All Rights Reserved.