



Bulletin No.: PIT6040
Published date: 07/12/2023

Preliminary Information

PIT6040 Upfitter Aux Switch ON LED Indicators Inoperative If More Than One Switch Is On

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2023	All	All	All	All
Chevrolet	Silverado 2500/3500	2024	All	All	All	All
GMC	Sierra 1500	2023	All	All	All	All
GMC	Sierra 2500/3500	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9L7 Aux Upfitters Switches
Condition	Some customers may comment that the aux switch "on" indicators (shown below) do not illuminate if more than one aux switch is turned on. The aux switches do work regardless of how many switches are turned on, but the "on" indicators will go inoperative if more than one switch is turned on.
Cause	BCM calibration.



Correction:

To correct this concern, reprogram the BCM with the latest calcs in TLC/SPS2.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Version History

Version	1
Modified	07/12/2023 - Created on.



© 2023 General Motors. All Rights Reserved.