



Preliminary Information

PIC6513 Alert 332 in DIC (Driver Information Center)

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Bolt EV/EUV	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that when operating the vehicle with a key fob that has been registered in Teen Driver mode, a message "Alert #332" may appear int the Driver Information Center (DIC).
Cause	The cause of the condition may be a software anomaly associated with ICE vehicles and not EVs.

Correction

While the software fix is being developed, the customer may choose from either option below.

- 1) The customer may dismiss the message in the Driver Information Center (DIC) without adversely impacting the safety or performance of the vehicle. The message may return on the next key cycle with the Teen Driver registered key fob.
- 2) The customer may unregister the key fob to eliminate the message from appearing in the Driver Information Center (DIC). But will lose all teen driver safety systems settings and report card data. Refer to the Vehicle's Owner Manual for instructions on adding/removing Teen Driver key fobs.

Note: This PI will be updated when the software fix is available.

Customer Information

Teen Driver is a configurable feature that lets you activate customizable vehicle settings associated with a key fob, to encourage safe driving behavior. It can limit certain vehicle features, and it prevents certain safety systems from being turned off. An in-vehicle report card gives you information on driving habits and helps you to continue to coach your new driver.

Version History

Version	1
Modified	07/26/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.