

MAS003652 RU 23-29

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Rapid Update 642 GranTurismo – Light Bar Bezel Replacement

TECHNICAL SERVICE OPERATIONS



DATE: JULY 12 2023

Certain Maserati GranTurismo (189) MY24 listed in MODISCS+ are involved in a Rapid Update to replace the license plate lamp moulding.

This action is needed because the old component was affected by a detachment phenomenon. The new component has a higher quality than the previous one and brings a better aesthetic appeal to the vehicle.

We remind you that all Rapid Updates must be performed the first time the vehicle enters the workshop, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Likewise, for cars in Stock Dealer/PDI, it is necessary to carry out all campaign operations before delivery to the final Customer, as prescribed by the White Book and explicitly reported in the Pre-delivery check list.

Please read and review this bulletin first before starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions. (Maseratitechsupport@maserati.com)


Thank You for your continued support and cooperation.

Maserati Americas
Aftersales Dept.

Overview

 All images shown in this bulletin are for illustrative purposes only

This action is needed due to the **old black-painted** moulding could be affected by detachment in case of thermal stress (heavy sun exposure, parking in hot area, etc..).



The **new** component, instead, have a **black-chrome finishing** that do not present the same defects giving a more luxury feeling to the car.



Procedure

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Take all the necessary precautions to avoid causing damage to the bodywork and, following the procedure in the workshop manual, proceed to replace the license plate lamp molding:
 - a. **9.15.266 - LICENSE PLATE LAMP MOULDING - Removal/refitting or replacement**
3. Refit all the parts you have removed following the removal procedure in reverse order.
4. Procedure complete.

Spare Parts

Please order the following PNs:

Spare parts	PN	QTY
LICENSE PLATE LAMP MOULDING	670313631	1

Warranty Claim

Fill in the relative Warranty Claims as follows:

Description	Code
Campaign Number	642
Warranty Code	23
Fault Code	063
Component Code	9.15.266
Operation Code	9.15.266.0 (0,40 h)