

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



MASTERS OF CARE

Rapid Update 643 MC20 – Door gasket check



DATE: JULY 20 2023

Certain Maserati MC20 (M240) MY23 listed in MODISCS+ are involved in a Rapid Update to verify the conformity of the door seals.

In fact, due to a problem during the supplier's production process, some cars may have white spots on the seals. This is a purely aesthetic problem that does not affect the functionality of the component in any way.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions. (Maseratitechsupport@maserati.com)

Thank You for your continued support and cooperation.

Maserati Americas
Aftersales Dept.

Overview

 All images shown in this bulletin are for illustrative purposes only

This action is needed to avoid white spots phenomena on the door seats that could happens during the life of the component.



OK



KO

Example

Procedure

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Replace the component, referring to the correct procedure in the workshop manual:
 - **9.34.096 GASKET FOR RH SIDE EDGE MOLDING - Removal-Refitting or Replacement**
 - **9.34.097 GASKET FOR LH SIDE EDGE MOLDING - Removal-Refitting or Replacement**
3. Procedure complete.

Spare Parts

Please order the following PNs:

Spare parts	PN	QTY
RH FRONT WINDOW CONTOUR SEAL	670216650	1
LEFT FRONT WINDOW CONTOUR SEAL	670216651	1

Warranty Claim

Fill in the relative Warranty Claims as follows:

Description	Code
Rapid Update Number	643
Warranty Code	23
Fault Code	063
Component Code	9.34.096
Operation Code ▪ Right gasket replacement ▪ Left gasket replacement	9.34.096.0 (0.20 h) 9.34.097.0 (0.20h)