

GPOP - Issue Review System

Part Number: 68411073A\$

Part Description: Sunroof power express open/close

Issue Description: Due to Dual Pane Sunroof switches being returned with no trouble found, proper diagnosis and testing needs to be done before replacing the switch. There is Diagnostic and Testing documentation available for this part in service Library to check the switch before replacing the part. For additional assistance, contact FCA Redacted Content. If no response in 15 minutes, proceed with repair.