



## STAR ONLINE PUBLICATION



**Case Number:** S2323000045

**Release Date:** June 2023

**Symptom/Vehicle Issue:** Stamping Mark On Under Hood Reinforcement.

**Customer Complaint/Technician Observation:** The customer or technician may observe that a mark is present on the underside of the hood assembly to the left of the hood striker (facing the vehicle).

**Discussion:** The mark, if like the figure below, is found it is normal and does not affect operation. The hood should not be replaced, or metal finished for this mark.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**