

<b>REFERENCE:</b>	<b>TSB:</b> 23-078-23 <b>GROUP</b> 23 - Body	<b>Date:</b>	June 27, 2023	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2023 (B1) Jeep Renegade</b> This bulletin applies to vehicles built on and after March 24, 2023 (MDH 0324XX) and on and before May 25, 2023 (MDH 0525XX).	<b>MARKET APPLICABILITY:</b>			
		<input type="checkbox"/> NA		<input type="checkbox"/> CH	
		<input type="checkbox"/> EE		<input type="checkbox"/> IAP	
		<input checked="" type="checkbox"/> SA		<input type="checkbox"/> MEA	
<b>CUSTOMER SYMPTOM:</b>	Excessive noise in the rear of the vehicle.				
<b>CAUSE:</b>	Cargobox missing (Fig. 1).				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-192, date of issue June 27, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. This RSU will expire 18 months after the date of issue.



**Fig. 1**  
**Cargobox Missing**

**REPAIR SUMMARY:**

This bulletin involves adding the cargobox to the vehicle.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-21-16-91	Cargobox - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.
23-21-16-92	Cargobox - Inspect and Install (0 - Introduction)	6 - Electrical and Body Systems	0.1 Hrs.
Failure Code	ZZ	Service Action	

**SPARE PARTS:**


Qty	Part No.	Description	Notes
1	7095207 South America	Cargobox Left Side	
1	7095208 South America	Cargobox Right Side	

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. **This RSU only applies to vehicles on the RSU VIN list.**

**REPAIR PROCEDURE:**

1. Open the rear hatch.
2. Lift up on the load floor.
3. Install the left and right cargoboxes (Fig. 2) .



**Fig. 2**  
**Cargoboxes Installed**

- 1 - Left Cargo Box  
2 - Right Cargo Box

4. Close the load floor.
5. Close the rear hatch.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*