

## GPOP - Issue Review System

**Part Number:** 68183751A\$, 68183752A\$

**Part Description:** Power window switch Passenger

**Issue Description:** Before replacing this part, please follow the service procedures to properly diagnose which include:

- 1) Verify if there are any external objects that could interfere with the switch functionality
- 2) Check if the Switch is properly connected to the harness.
- 3) Since this switch uses LIN communication, monitor the door control switch commands through the Body Control Module (BCM), with a diagnostic Scan tool monitor.

Please note that this switch does not have the express Up/Automatic Roll up Feature. By design it only has the Express Down/Automatic Roll Down Feature. If after following the procedures, the switch is still faulty. Please replace the switch.