

**On-car analysis list from July August 22nd, 2023
please contact VW Helpline before attempting repair**

| | Models | MY | Engine | Transmission | Topic | Customer Complaint |
|-------------------|---|-----------|---------------|---------------------|--|--|
| Powertrain | Tiguan | 21-23 | All | All | MIL-on P0442 | Customer states MIL-on, fault P0442 stored in ECM memory (Untouched vehicle) |
| | Atlas, Atlas Cross Sport | 23 | All | All | Exhaust/Heat shield noise | Customer states rattle from below the vehicle (Untouched vehicle) |
| | Tiguan | 23 | All | All | MIL-on P04F0 | Customer states MIL-on, P04F0 stored in ECM memory (Untouched vehicle) |
| | Atlas, Atlas Cross Sport | 23 | 3.6L CDVC | All | MIL-on P0461 | Customer states MIL-on, fault P0461 stored in ECM memory (Attach MVBs IDE03472 and IDE03473 from Address 17 to GFF log) |
| Body | ID.4 | 23 | All | All | Sun Visor | Customer states sun visor is loose/broken (Untouched vehicle) |
| Electric | Tiguan | 22-20 | All | All | Seat Fault B201000, B135354 and/or B135454 | Customer states seat memory is inoperative (Must have B201000, B135354 and/or B135454 in address 36) (Untouched vehicle) |
| | Atlas, Cross Sport, Jetta, Taos, Tiguan | 22-23 | All | All | Key Battery | Customer states key FOB lock/unlock functions do not work via button press (not KESSY). (Must have B147918 and/or B147A18 in Address 09) |
| | ID.4 | 23 | All | All | Seat Fault B135554 | Customer states seat memory is inoperative (Must have B135554 in address 36) (Untouched vehicle) |
| | Tiguan | 22-23 | All | All | Seat Belt | Customer states seat belt won't retract |