

Safety Recall and Service Campaign - Technician Certification Requirements

Posted 7/27/2023

IMPORTANT:

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right. Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

	Description					Cert	ficatio	n Leve	l Requi	reme	ents					I
Safety Recall or Service Campaign		Required Courses			Cert	ified			Ex	pert					Special	Additional Requirements
Safety Recall of Service Campaign		Required Courses	Maint							_			Mast	MD	Courses	Additional Requirements
		TIC206A		EG	DT	CH	EL	EG	DT (CH	EL	HY		+	_	
23TC05	Software Update 23TC05, EV Charging Performance + Display Software Update, Certain 2023 bZ4X	TEC100E														
23TA04	Certain 2022-2023 Model Year Corolla Cross	TIC206A														
	Passenger Airbag May Not Deploy as Designed	TICZOOA														
23TA05	Certain 2023 Model Year Camry and Camry HV	T4535														
23TJ01	Potential Loss of Vehicle Control	TICOCA						-	_	_						
231301	Second Key Delivery Program Customer Support Prgoram 22TE05 - 2019-2021 RAV4, RAV4HV, and RAV4 Prime - Coverage for Roof Rail Water	TIC206A								-						
22TE05	Customer Support Prgoram 221E05 - 2019-2021 RAV4, RAV4HV, and RAV4 Prime - Coverage for Roof Rail Water Leak			~	✓	✓	~	~	✓	~	✓	~	✓	~		
23TD03	Certain 2022-2023 GR86 - DCM Reprogram	TIC206A														
CSP 23TE06	Certain 2017 Prius V	T553														
CSF 231E00	Coverage for Brake Booster and Brake Booster Pump Assemblies	TIC209A														
CSP 23TE07	Certain 2016 Prius V	T553														
	Coverage for Brake Booster and Brake Booster Pump Assemblies	TIC209A														
	Certain 2022-2023 Tundra HV															
Safety Recall 23TA03	Certain 2022-2023 Tundra															
(INTERIM 23TB03)	Tonneau Cover May Come Off While Driving	TIC206A														
	Certain 2022-2023 Model Year Tundra HV and Certain 2023 Model Year Tundra	TICZUBA						-		-						
Safety Recall 23TA02	Instrument Panel LCD Montitor May Go Blank While Driving	TIC206A														
	Certain 2012 – 2017 Model Year Prius V and 2010 - 2015 Model Year Prius	TICZOOA								+						
CSP 23TE03	Extension of Coverage to the Intelligent Power Module (IPM)											~	✓	✓		
	Certain 2012 – 2017 Model Year Prius V and 2010 - 2015 Model Year Prius									7						
CSP 23TE02	Extension of Coverage to the Intelligent Power Module (IPM)											✓	~	~		
5.5 . 0 . 11.2274.04	2021 Model Year RAV4 Prime															
Safety Recall 23TA01	Vehicle May Lose Motive Power While Driving	TIC206A														
CSP 23TE01	Customer Support Program 23TE01 - Multiple Models Coverage for High Pressure Fuel Pump - Low Pressure Fuel	TIC201A														
CSP 22TE09	Customer Support Program 22TE09 - Certain 2019 – 2022 Model Year Rav4 HV (AWD Only) Coverage for HV Floor											1	✓	1		
	Under Wire Harness and Rear Traction Motor Cable Corrosion															
Safety Recall 22TA06	Certain 2023 Model Year bZ4X											1	✓	✓		
	Potential Loss of Vehicle Control								-	-	-			-		
SSC 22TC11	Certain 2023 Model Year bZ4X Software Update - DC Cold weather Charging											✓	✓	✓		
	Certain 2023 Model year bZ4X	TIC206A					-	-	-	+						
SSC 22TC09	bZ4X Vehicle Identification number (VIN) Verification	SC19A														
	Certain 2023 Model Year bZ4X									7		1	·	_		
LSC 22TD05	Software Update for "Car Finder" Feature											V	·	·		
	Certain 2022 Model Year RAV4													1		
SSC 22TC10	Certain 2022 Model Year RAV4 Hybrid	TER022A TIC206A											l	1		
	Software Update for the Hybrid Powertrain Control Module	TICZODA														
	Certain 2022 Model Year Tundra Vehicles	Ì		1				\neg		\dashv				1		
Safety Recall 22TA11	Electronic Parking Brake (EPB) May Not Engage or Disengage Properly	TIC206A												1		
SSC 22TC06	Certain 2022 Model Year C-HR	SC19A														
	Certain 2022 - 2023 Model Year Tacoma Vehicles							T		Ţ	Ţ	1				
Safety Recall 22TA09	Upper Child Seat Anchor Welds May Failure During a Crash							~	~	✓	✓	~	✓	~		
	<u>, </u>			1										1		I

	Description	1				Certific	ation Le	vel Re	quirem	ents					
Safety Recall or Service Campaign		Required Courses			Certifi	ed			Expert					Special	Additional Requirements
Sarety Recail of Service campaign	Description	Required Courses	Maint									Mast	MDT	Courses	radiiona nequi emenes
				EG	DT	CH EI	. EG	DT	CH	EL	HY				
	Certain 2022 Model Year Camry														
	Certain 2022 Model Year Camry Hybrid														
	Certain 2021-2022 Model Year Rav4														
SSC 22TC05	Certain 2021 Model Year Rav4 Hybrid	TIC201A													
330 221003	Certain 2022 Model Year Avalon Hybrid	TICZOTA													
	Certain 2022 Model Year Highlander Hybrid														
	Certain 2022 Model Year Sienna Hybrid														
	Crankcase Case Vent														
	Certain 2022 Model Year RAV4														
Safety Recall 22TA08	Certain 2022 Model Year RAV4 Hybrid														
Salety Recall 221A06	Certain 2022 Model Year RAV4 Prime	TIC206A													
	Airbag May Not Deploy Properly	-		-			-	_			-				
SSC 22TC08	Certain 2022 Model Year Tundra Vehicles														
	Engine ECU Software Update	TIC206A													
Safety Recall 22TA07	Certain 2022 Model Year Tundra														
	Panoramic View Monitor System - Potential failure to display rearview image	TIC206A													
ccc 22	Certain 2020 Model Year Corolla Vehicles													1	
SSC 22TC07	Engine ECU Software Update	TIC206A												1	
	Cortain 2021 Model Year Mirai			+		-	+	1			-+				
LSC 22TD01	Certain 2021 Model Year Mirai Software Update for EV Control Computer	TIC206A												1	
	Software Opusite for EV Control Computer	TICZUBA		\vdash											
	L														
LSC 22TD04	Certain 2021 Model Year Sienna Certain 2021 Model Year Venza														
LSC 221D04	Accessory Dash Camera Firmware Reprogram	TIC206A													
	, access, passi cancia i i i i i i i i i i i i i i i i i i														
				\vdash											
Safety Recall 22TA05	Certain 2022 Tundra and Tundra Hybrid Vehicles Rear Axle Shafts May Separate from Vehicle During Driving	T351													
		-		-			-	_			-				
Safety Recall 22TA01	Certain 2021 Venza Hybrid Vehicles Rear Turn Signal Lamps May Become Dim or Deactivated	TICOOCA													
	Certain2020-2022 Model Year Highlander Hybrid	TIC206A		-	_		-	-		-	-				
	Certain 2021-2022 Model Year Mirai														
	Certain 2021-2022 Model Year RAV4 Prime														
Safety Recall 22TA03	Certain 2022 Model Year RAV4 Hybrid	TICOGGA													
	Certain 2021-2022 Sienna Hybrid	TIC206A													
	Certain 2021-2022 Venza Hybrid Vehicle Stability Control System May Not Default to "On"														
				H											
Safety Recall 21TA09	Certain 2018-2019 Model Year Camry Sudden Loss of Power Braking Assist May Occur	TIC201A													
				-			-	-							
Safety Recall 22TA04	Certain 2022 Model Year Tundra														
•	Panoramic View Monitor System - Potential failure to display rearview image	TIC206A		-							_				
LSC 22TD03	Certain 2022 Model Year GR86 DCM (Data Communication Module) Activation	SC19a													
	DCW (Data Communication Windure) Activation									<u>_</u>					
	Certain 2018-2021Model Year Tundra Vehicles														
Safety Recall 21TA06	Potential Increased Risk of Vehicle Fire	T652													
	Certain 2021 Model Year Highlander Vehicles														
LSC 22TD02	Sealant for a Seam near the Fuel Inlet	TIC206A													
	Second of Second and the fact that	TICZUUA													
	Certain 2018 Model Year Camry & Certain 2018 Model Year Camry Hybrid														
CSP 22TE02	Coverage for Steering Intermediate Shaft	T453													
SSC 22TC04	Certain 2021 Model Year Mirai Vehicles														
330 221007	Software Update for the EV Control Computer	TIC206A													
	Certain 2021 Model Year C-HR, RAV4 Prime, Tundra								1 1		ſ			1	
SSC 22TC01	Certain 2021-2022 Model Year 4Runner, Highlander, Highlander HV, Prius Prime, Sequoia, Tacoma	T100000												1	
	Certain 2022 Prius Data Communication Module (DCM) Reprogramming	TIC206A													
	Certain 2021 Model Year C-HR Vehicles			T		_	1	1							
Safety Recall 22TA02	Pre-Collision System (PCS) Inoperative without Warning Indicator	TIC206A												1	
	Certain 2007-2021 Model Year Tundra Vehicles	110200A	 	\vdash	— l	-	+				-+			 	
Equipment Recall 21TH01	Certain 2008-2022 Model Year Sequoia Vehicles	T453													
	Potentially Defective Power Steering Gear Assemblies														
Safety Recall 21TA10	Limited Service Campaign 21TD02 (Remedy Notice), Certain 2021 Model Year Tacoma Vehicles, Additional Remote Keyless Entry Key	T453													
CSP 21TE04	Certain 2017-2018 Model Year Avalon Hybrid - Certain 2017 Model Year Camry Hybrid - Coverage for Brake Booster and Brake Booster Pump	T553 / T071							1 1		ſ			1	
	Assemblies			\vdash			+	1	\vdash		-+				
Safety Recall 21TA08	Certain 2022 Model Year Sienna Vehicles														
<u> </u>	Second-Row Outboard Seat Belts Could Tear in a Crash	TIC206A												l	

	Description	1	1			Ce	rtificat	ion Le	vel Rec	uirem	ents				1	
Safatu Basall or Sarvisa Compaign		Beautiand Courses			Cer	tified				Expert					Cassial	Additional Requirements
Safety Recall or Service Campaign		Required Courses	Maint										Mast	MDT	Special Courses	Additional Requirements
				EG	DT	CH	EL	EG	DT	CH	EL	HY		1		
Safety Recall 21TA05	Certain 2019 - 2020 Model Year Yaris Sedan Certain 2020 Model Year Yaris Hatchback & Yaris R	TICOOCA														
	Vehicle May Stall During Driving at Higher Speeds	TIC206A												<u> </u>		
CSP 21TE03	Certain 2016 Model Year Avalon Hybrid, Certain 2015-2016 Model Year Camry Hybrid, Certain 2011-2013 Model Year Highlander Hybrid, Coverage for Brake Booster and Brake Booster Pump Assemblies	T553 / T071														
Consumer Advisory 21TG01	Certain 2013-2018 Model Year RAV4, 12-Volt Battery Size and Installation Inspection	TIC206A														
Safety Recall 21TA07	Certain 2022 Model Year Prius and Prius Prime Vehicles, Vehicle May Lose Motive Power While Driving	TIC206A														
SSC 21TC02	Certain 2021 Model Year Supra Vehicles, Improper Programming in a 21V Battery Management System	TIN519B														
Safety Recall 21TA01	Certain 2009 – 2015 Model Year Venza Vehicles															
	Non-Deployment of Side and Curtain Shield Airbags May Occur	TIC206A												1		
SSC 21TC06	SPECIAL SERVICE CAMPAIGN 21TC06 (Remedy Notice) - Certain 2021 Model Year Prius - Pre-Collision System Software Update	TIC206A														
Safety Recall 21TA03	Certain 2018-2019 Model Year 86 (Remedy Notice) - Vehicle May Stall if Low-Pressure Fuel Pump Becomes Inoperative	TIC206A														
LSC 21TD02	Limited Service Campaign 21TD02 (Remedy Notice), Certain 2021 Model Year Tacoma Vehicles, Additional Remote Keyless Entry Key	TICOCA														
Safety Recall 21TA04	Certain 2020-2021 Model Year Supra; Potential Increased Braking Distance	TIC206A TIN519B			L			L							<u> </u>	
LSC 21TD03	Certain 2016-2019 Model Year Double Cab Tacoma Vehicles, Center High-Mounted Stop Lamp Assembly - Water Leak	TIC206A														
SSC 21TC05	Certain 2020-2021 Model Year Highlander; Programming Adjustment for Low Fuel Light	TIC206A														
SSC 21TC03	Certain 2017-2019 Model Year Highlander Hybrid, 2018-2020 Model Year Camry Hybrid, 2019 Model Year Avalon Hybrid, 2019 Model Year Rav4; Low-Pressure Fuel Pump	TIC206A														
SSC 21TC04	SPECIAL SERVICE CAMPAIGN - 21TC04 - Certain 2021 Model Year C-HR - Incorrect Programming for Rear Seat Belt Reminder Indicator													İ		
CSP 20TE06	CUSTOMER SUPPORT PROGRAM 20TE06 - Certain 2021 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	TIC206A TIC206A														
CSP 20TE05	CUSTOMER SUPPORT PROGRAM 20TE05 - Certain 2020 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	TIC206A														
CSP 20TE04	CUSTOMER SUPPORT PROGRAM 20TE04 - Certain 2019 - 2020 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	TIC206A														
Safety Recall 20TA02	Certain 2014 FJ Cruiser; 2014-2015 4Runner, Landcruiser; 2017-2020 Sienna, Tacoma; 2018-2020 Avalon, Corolla, Camry, Tundra; 2019-2020 RAV4; 2019 Corolla Hatchback; 2018-2019 Sequoia, Highlander, Landcruiser, 4Runner; Vehicle May Stall During Driving at Higher Speed	TIC206A														
CSP 21TE01	Certain 2012-2014 Model Year Prius C - Coverage for Brake Booster and Brake Booster Pump	T553 / T071														
Safety Recall 20TA16	Certain 2020-2021 Model Year Supra,Potential Fuel Tank Leak							✓	✓	~	✓	✓	✓	✓	TIN519B	
Safety Recall 20TA17	Certain 2020 Model Year Avalon, RAV4, RAV4 Hybrid, Certain 2020 - 2021 Model Year Avalon Hybrid, Steering Column Issue May Affect Airbag Performance					✓		✓	✓	✓	✓	✓	✓	✓		
CSP 20TE08	Certain 2018 Model Year Prius c Vehicles; Coverage for Specific Cracks in the Tail Lamps Potentially Allowing Water Intrusion			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall 20TA15	Certain 2021 Model Year RAV4 Prime; Headlamp Beam Could be Improperly Adjusted Horizontally			✓	V	✓	✓	✓	✓	✓	✓	✓	✓	V		
CSP 20TE03 Safety Recall 20TA14	Certain 2019 – 2020 Model Year RAV4; Adventure and Limited grade AWD only, Coverage for Front Transfer Case Electro-Magnetic Clutch Certain 2020 Model Year Highlander, Highlander HV; Potential Improper Deployment of Seat Mounted Side Air Bag			/	✓ ✓	/	/	_	✓ ✓	/		_	· ·	✓ ✓		
CSP 20TE10	Certain 2013-2015 Prius; 2014-2017 Prius V; Hybrid System Software Update Extension of Coverage to the Intelligent Power Module (IPM)			Ė	Ė	H	Ė	Ė	Ė	•	-	~	7	·		
CSP 20TE07	Certain 2012-2014 Model Year Prius V; Coverage for Brake Booster and Brake Booster Pump Assemblies											✓	✓	✓		
SSC 20TC03	Certain 2019 Model Year Yaris Sedan; Engine Control Module Reprogram			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall 20TA13	Certain 2020 Model Year Supra; Headlamp Adjustment Plugs Installed in Incorrect Locations			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall 20TA01	Certain 1997-1998 Model Year Supra; 1998-1999 Model Year Celica; 1998-2000 Model Year RAV4; 1998-1999 Model Year RAV4 EV Airbag May Not Deploy Properly or Airbag Inflator May Rupture						~	~	~	~	✓	✓	~	~	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall 20TA08	Certain 2019-2020 Rav4; 2019-2020 Rav4 HV; Potential Loss of Vehicle Control due to Front Lower Suspension Arm Separation					✓		✓	✓	✓	✓	✓	✓	✓		
Safety Recall 20TA12	Certain 2018-2020 Tundra Front Turn Signal Brightness						✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall 20TA11	Certain 2019-2020 Rav4; 2020 Rav4 HV Potential Loss of Power Steering Assist				$ldsymbol{oxed}$	✓			Ш	✓			✓.	V		
Safety Recall 20TA10	Certain 2013-2015 Prius; 2014-2017 Prius V; Hybrid System Software Update Certain 2020 Avalon HV, Camry, Camry HV; 2019-2020 RAV4, RAV4 HV; Certain Engine Blocks Can Cause Engine Failure Leading to Engine Stall (non-	1	-	1	_		1		$\vdash \vdash$			✓	✓	·	1	
Safety Recall 20TA04	hybrid) and/or Fire Risk			✓				✓	✓	✓	✓	✓	~	✓	1	
Safety Recall 20TA07	Certain 2020 Corolla Hatchback; Backup Lamps May Become Inoperative				_	_		1		✓		V	·	V		
SSC 20TC01	Certain 2012 Tacoma; Air Injection Pumps and Air Switching Valves		-	✓	~	·	✓	~	✓	✓	·	· /	✓	✓ ✓	1	
Safety Recall 20TA05 Safety Recall 20TA06	Certain 2011-2012 Corolla , Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur Certain 2020 Highlander, Potential Vehicle Stall While Driving			/	/	1	/	1	/	/	·	·	·	· ·		
LSC 20TD01	Certain 2012-2019 Sequoia, Potentially Incorrect Carpet Floor Mats			·	/			·	·	·	·	· /	·	· /	1	
Safety Recall 20TA03	Certain 2011-2019 Corolla, 2012-2018 Avalon, 2013-2018 Avalon HV, 2011-2013 Matrix Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur										✓	✓	✓	1		
Safety Recall 19TA20	Certain 2020 Supra; Headlamp(s) May Become Inoperative							✓	✓	✓	✓	✓	✓	✓	TIN519B	<u> </u>
Safety Recall 20TA04	Certain 2020 Avalon HV, 2020 Camry, Camry HV, 2019-2020 Rav4, RAV 4 HV; Certain Engine Blocks Can Cause Engine Failure Leading to Engine Stall (non-hybrid) and/or Fire Risk	TIC201A														
Safety Recall 19TA22	Certain 2020 Corolla, Corolla HV, 2019-2020 C-HR; Certain Rear Seat Belt Lock(s) May Become Inoperative			✓.	V			V	✓	✓	✓.	V	✓.	✓		
SSC 19TC04	Certain 2017-2019 Highlander HV; Oil Cooler Pipe	1		1	1	1	1	1	1	1	1	1	1	1	1	1
Safety Recall 19TA21 SSC 19TC06	Certain 2019 Prius; Combination Meter Display May Become Inoperative	 		✓ ✓	✓ ✓			✓	✓ ✓	V	✓	✓ ✓	✓	✓ ✓	1	
22C TA1C0p	Certain 2020 Camry, Avalon; Engine ECU Reprogram	1			ı *	<u> </u>	. *		,	•	,				1	I .

		Certifica									nents				1	1
Sefet. Beerli es Semiles Semanies	Description	Danishad Cassas			Cert					xpert	t				Constal.	Additional Requirements
Safety Recall or Service Campaign	Description	Required Courses	Maint										Mast	MDT	Special Courses	Additional Requirements
				EG	DT	CH	EL	EG	DT	CH	EL	HY				
LSC KOD	Certain 2011-2017 Tacoma Frame Corrosion Resistant Compound (CRC) Application			1	1	✓	✓	✓	✓	✓	✓	✓	✓	✓	SCK0D	
Safety (Noncompliance) Recall 19TA19	Certain 2020 Supra Back Up Camera Display - Brightness and Contrast Settings			/	/	/	1	/	✓	/	1	1	/	✓	TIR019A	
Safety Recall KOL	Certain 2020 Corolla Hybrid, 2019 Rav4, 2019-2020 Prius Prime, 2019 Prius; Potential Loss of Power Brake Assist					~				✓			√	1		
LSC KOP / CSP 19TE12	Certain 2013-2019 4Runner, 2011-2017 Land Cruiser, 2013-2017 Prius, 2012-2017 Prius V, 2016-2017 Mirai Safety Connect System - Vehicle Location			1	/	1	~	1	~	/	/	1	·	~		
250 101 / 051 251212	Inaccurate															
Safety Recall KOQ	Certain 2003-2008 Corolla, 2005-2008 Matrix Passenger Airbag May Not Inflate Properly						1	✓	~	✓	~	1	✓	~	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall KOK	Certain 2018-2019 Prius C, Potential Loss of Motive Power While Driving											✓	✓	✓		
Safety (Noncompliance) Recall KON	Certain 2019 Rav4, 2019 Rav4 HV, Backup Camera Display May Not Operate			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety (Noncompliance) Recall KOM	Certain 2019 Camry, Passenger Front and Knee Airbags May Not Deploy as Designed			·	·	·	·	V	·	<u> </u>	·	·	·	· ·		
Safety Recall J05 Safety Recall K0G	Certain 2008-2019 Landcruiser, Passenger Airbags Could Deactivate Certain 2019 Sienna Potential Unintended or Non-deployment of Passenger Side Front Seat and Curtain Shield Airbags			✓ ✓	✓	4	✓ ✓	V	·	<u> </u>	· ·	✓ ✓	· /	✓ ✓	1	
Safety Recall KOG Safety Recall KOF	Certain 2019 Sienna Potential Unintended or Non-deployment of Passenger Side Front Seat and Curtain Shield Airbags Certain 2015-2017 Yaris, Front Seat Side and Curtain Shield Airbags May Not Deploy as Intended			· /	·	· /	·	· /	·	·	· ·	·	· /	· ·	1	
SSC KOB	Certain 2019-2017 Tans, Front Seat Side and Curtain Shield Andags way Not Deploy as intended Certain 2018-2019 Tacoma, Tundra Millimeter Wave Radar Sensor			·	· /	· /	· /	· /	· /	·	· /	·	· /	· /	 	
Safety Recall J07	Certain 2019 Corolla Hatchback Potential Loss of Power While Driving				· /			_	·			Ė	·	1		
SSC KOA	Certain 2018 Tundra, Sequoia, Camry, Sienna Engine ECU Software Update			✓	✓	✓	✓	/	✓	✓	✓	✓	✓	✓		
Safety (Noncompliance) Recall KOI	Certain 2019 Avalon and Camry HV Fuel Filler Pipe			✓	~	✓	✓	✓	✓	~	✓	✓	✓	✓		
Safety Recall JS5	Certain 2008-2019 Landcruiser, Passenger Airbags Could Deactivate			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall JOV	Certain 2010-2014 Prius, 2012-2014 Prius V Hybrid System Software Update											✓	✓	✓		
Safety Recall J06	Certain 2018-2019 Tacoma Brake Master Cylinder Replacement					✓				✓			✓	✓		
Safety Recall JOW	Certain 2003-2006 Scion xA Center Airbag ECU Replacement					لبا	V		L.I		✓	<u> </u>	V	V	1	
Safety (Noncompliance) Recall J08	Certain 2019 Tundra Weight Label Replacement			✓	✓	✓	✓	√	✓	✓	✓	✓	·	· /	1	1
Safety Recall J02	Certain 2013 FR-S Valve Spring Replacement							✓					· /	✓ ✓		
SSC JOU	Certain 2008-2015 Scion xB, 2011-2016 Scion tC TRD Brake Kit				·	✓ ✓	1	/		·			·	· /	1	
SSC JOR Safety (Noncompliance) Recall JOZ	Certain 2018 Camry, Camry Hybrid, 2016-2018 Prius, 2017-2018 Prius Prime Intelligent Clearance Sonar (ICS) System Reprogram Certain 2018-2019 Tundra Load Carrying Capacity Modification Label			·	· /	·	·	·	· /	·	· /	·	·	· ·		
Safety (Recall JOY	Certain 2019 C-HR Rear Axle Hub Bearing Bolt	1		Ė		1		_	-	· /	<u> </u>	<u> </u>	· /			
Safety Recall JOX	Certain 2018-2019 Tundra, Sequoia; 2019 Avalon & Avalon HV SRS Sensor Software Update			/	~	·	✓	/	✓	_	/	✓	· /	1		
Safety Recall JOT	Certain 2016-2018 Prius Engine Wire Harness											✓	✓	✓		
Safety Recall JOS	Certain 2012 Avalon Front Seat Belt Buckle Inspection and Replacement			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
SSC JON	Certain 2016-2017 Tacoma Blower Motor Replacement			✓	✓	✓	✓	1	✓	V	√	✓	✓	· /		
SSC JSD	Certain 2014-2017 Corolla, 2017 Corolla iM, 2016 Scion iM Software Update for CVT				✓			✓	✓	✓	~	✓	· /	✓ ✓		
Safety Recall JOM Safety Recall JOK	Certain 2018 Camry Oversized Pistons Certain 2017 Sienna and Tacoma, 2018 Camry and Highlander Vacuum Pump			1				·					· /	· ·	1	
Safety Recall JOF	Certain 2016 Prius Airbag Sensor			Ė			1	/	✓	/	_	1	·	· /		
Safety Recall JOG	Certain 2018 Camry Fuel Delivery Pipe			✓	✓	✓	1	/	✓	·	✓	✓	✓	1		
Safety Recall J0J	Certain 2018 Sienna Wheel Replacement		1	1	~	✓	√	~	✓	√	~	1	~	·	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety Recall JOI	Certain 2017 Tundra Rear Seat Low Torque			✓	~	~	✓	/	1	/	1	1	√	1		SCISA
Safety (Noncompliance) Recall JOH	Certain 2018 Tundra and Sequoia Software Update for Vehicle Stability Control System			✓	~	✓	✓	✓	✓	~	✓	✓	✓	✓		
Safety Recall JOA,JOB,JOC	Certain 2003-2010 Matrix, 2003-2013 Corolla, 2003-2006 Tundra, 2002-2007 Sequoia, 2010-2016 4Runner, 2004-2005 Rav4, 2011-2013 Sienna, 2008-2012 x8, 2007-2012 Yaris Sedan, 2007-2011 Yaris Hatchback passenger airbag module						√	~	~	√	√	√	~	~	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall G04 Phase 2	Certain 2011-2016 Sienna Power Sliding Door Mobility Vehicle			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
SSC HOX	Certain 2016-2017 Mirai EV Control ECU Software Update			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall HOR	Certain 2012-2015 Prius PHV Electric Vehicle Fuse Fracture							_				·	√	· /		
Safety (Noncompliance) Recall HOZ SSC HOY	Certain 2017 Sienna and Tacoma, 2017-2018 4Runner and Tundra, 2018 Highlander and Rav4 Load Carrying Capacity Modification Label Certain 2018 Tundra and Sequoia Center Air Bag Software Update			✓ ✓	✓ ✓	✓ ✓	✓ ✓	√	✓ ✓	<u>✓</u>	·	✓ ✓	✓	√	1	
Safety Recall HOV	2005-2007 and 2009-2010 Sienna Shift Lock Solenoid Assembly			·	·	·	·	·	✓	· /	·	·	·	·		
Safety (Noncompliance) Recall HOW	Certain 2018 C-HR Electronic Parking Brake Reflash			√	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
LSC H0T	Certain 2018 Camry Rear Wheel Arch Sealer Gap			✓	✓	✓	✓	✓	✓	✓	✓	V	V	V		
Safety Recall HOU	Certain 2016 Prius Inverter Assembly Replacement	!		\vdash		$\vdash \vdash$	_	/	1	_	1	✓	✓	✓ ✓	 	1
SSC HOP LSC HON	Certain 2017 Yaris Instrument Panel Wire Harness Certain 2018 C-HR Rear Bumper Garnish		1	1	/	1	·	·	·	·	·	·	· ·		SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of
																SC19A
LSC H0J	Certain 2007-2014 FJ Cruiser Fuel Tank			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	1	
LSC HOL	Certain 2018 C-HR Parking Brake Cover		✓	~	~	✓	✓	✓	✓	✓	*	1	V	·	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety Recall HOS	Certain 2008-2016 Landcruiser Driver Airbag Assembly	!		\vdash		$\vdash \vdash$			$\vdash \vdash$		✓	-	✓	✓	 	All to the second of the secon
LSC H0F	Certain 2005-2010 Tacoma, 2005-2008 Sequoia, and 2007-2008 Tundra CRC Application		✓	✓	~	✓	✓	✓	✓	✓	~	~	✓	✓	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety Recall H0H	Certain 2016-2017 Tacoma Crankshaft Position Sensor			✓	_	<u> </u>		✓	_				✓	✓ ✓	1	1
Safety Recall HOM	Certain 2016 Camry and 2016 Avalon CV Axles			\vdash	~	 			*		_	 			1	+
Safety Recall G04 Phase 1	Certain 2011-2016 Sienna Power Sliding Door	I					✓				~	1	✓	✓	SRG04	SRG04 Instructor Led course from the Region
Safety Recall HOK	Certain 2016 Tundra Knee Airbag Bolts			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Emission Noncompliance Recall H0I	Certain 2018 C-HR Emission Label Installation			✓	✓	✓	✓	✓	✓	V	✓	✓	✓	V		
Safety Recall H0G Safety Recall H0C	Certain 2016-2017 Tacoma Rear Differential Leak Certain 2016-2017 Tundra Bumper Reinforcement Brackets	 		/	_	✓ ✓	_	/	/	/	✓	./	✓	· /	1	
Safety Recall HUC SSC H0E	Certain 2016-2017 Fundra Bumper Reinforcement Brackets Certain 2016 -2017 MY Mirai Fuel Cell System Updates	 	-	·	·		·			·		·	· /	· /	+	1
SSC HOD	Certain 2010 -2017 Min Minar rule: Cen System Opulates Certain 2016 Scion iA & 2017 Toyota Yaris iA Certification Label	1		·		·			·			·	·	·	†	
2221100		•									•		•			•

			1			Certi	ificatio	n Leve	el Requ	ireme	nts					
					Cert	ified	Т			pert						†
Safety Recall or Service Campaign	Description	Required Courses	Maint			П			Ī	T			Mast	MDT	Special	Additional Requirements
				EG	DT	CH	EL	EG	DT	CH	EL	HY			Courses	
SSC GOY	Certain 2006-2008 MY RAV4 Muffler Inspection					✓				✓			✓	~		
LSC GOX	Certain 2016 MY RAV4 & RAV4 HV Power Rear Hatch ECU			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Expires November 30, 2019
Safety Recall G05	Certain 2016 Avalon and Certain 2017 Camry										1		1	/		
,	Incorrect Passenger Knee Airbag Fasteners			/	/	1	1	/	1	./	1	/	_	·		Expires October 31, 2019
LSC G02 SSC G0Z	Certain 2015-2016 Camry DSS ECU Update Certain 2017 MY Sienna Powertrain ECU Software Update			· /	·	·	·	·			·	· /	· /	·		expires October 31, 2019
Safety Recall GOC	Certain 2003-2006 MY Land Cruiser, 2005-2006 MY Sequoia, 2005-2006 MY Tundra, 2004-2006 MY 4Runner SRS ECU					Ė	Ť			_	·	-	·	· /		
Safety Recall GOW	Certain 2016 MY Prius Front Passenger Airbag										✓		✓	✓		
Safety Recall G01	Certain 2016 - 2017 MY Prius Parking Brake Cable Clip		✓	<	<	~	~	~	~	~	~	~	<	~	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety (Noncompliance) Recall G03	2016 MY Highlander Brake Fluid Reservoir Sensor Connector			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	~		
Safety Recall G0P/G0R/H0A	Certain 2006-2011 MY Yaris Hatchback & 2007-2012 MY Yaris Sedan, 2009-2013 Corolla, 2009-2013 MY Matrix, 2008-2015 MY Scion xB, 2010-2016 4Runner, and 2011-2014 Sienna Takata Airbag						1	✓	✓	~	~	✓	~	√	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall FOS	2009-2012 MY RAV 4 & 2012-2014 MY Rav4 EV Ft. Wiper Arm Crank Arm			✓	✓	~	✓	✓	✓	✓	✓	✓	~	~		
Safety Recall GOU	2010 - 2012 MY Prius & Prius Plug-in Curtain Shield Airbag										✓		✓	✓		
Safety Recall GOS	2015 MY Yaris Front Strut Bearing Inspection					✓				✓			✓	✓		
Safety Recall G0V	2006-2011 MY RAV4 Rear Lower Suspension Arm No.1									~			✓	✓	SCGOV SCGOVH	Technicians must also successfully complete SCGOV online and SCGOVH conducted by the Regions.
LSC GOT	Certain 2016 MY Prius Simple Advance Parking Guidance System			✓	✓						_	1	✓	V		
Safety Recall GOM	2015-2016 MY Toyota Prius V Emission Control Information Label	1	l	✓ ✓	✓ ✓	· /	✓	/				✓ ✓	✓	✓ ✓		-
LSC GOL LSC GOK	2016 MY Scion iA Spare Tire Pressure Adjustment 2016 MY Scion iA Inspection and Adjustment of Coolant Concentration	1	l	·	· ·	· /	<i>'</i>	· /	· /	,	·	·	·	·	-	+
Safety Recall GOJ	Certain 2016 MY Avalon, Avalon HV & Camry Occupant Classification System (OCS)	1	-	Ė	-	\vdash	$\dot{+}$	7	7	7	7	7	~	7	 	<u> </u>
Safety Recall GOI	Certain 2016 MY RAV4 Brake Actuator Inspection/Replacement					√	\dashv	\dashv	<u> </u>	·	\dashv	-t	· /	· /		
Safety Recall GOH	Certain 2016 MY Sienna Front Driver and Passenger Seat Belt Height Adjuster Replacement			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall G0G	2015-2016 MY Toyota Sienna Oxygen Sensor Replacement			✓	✓	✓	✓	✓			✓	✓	✓	✓		
Safety Recall GOF	2006-2012 MY Rav4, 2012-2014 Rav4 EV Rear Outboard Seatbelts			✓	✓	✓	✓	✓		✓	✓	✓	✓	✓		
Safety Recall G0E	Certain Model 2013 - 2016 MY Scion FR-S Ignition Key Interlock System (Automatic Transmission Models with Ignition Key ONLY)			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall F0V	Certain 2013-2015 MY Avalon, Avalon HV Pre-Collision System							✓	✓	✓	✓	✓	✓	✓	SCFOV	*If inspection determines the vehicle requires
SSC FOU	Certain 2010 - 2014 MY Tacoma 2TR-FE Vehicles Exhaust Pipe Replacement for Catalytic Converter			✓	✓	~	✓	✓	✓	✓	~	✓	✓	~		additional electrical repairs, it must be preformed by a technician who is expert or above
Safety Recall FOT	2016 MY Tacoma Driver Knee Airbag Module Bolts			✓	✓	✓	✓	✓	✓	✓		✓	✓	· /		
Safety Recall FOR	2012-2014 MY Prius V Software Update for Motor Generator ECU and Power Management ECU			/	/	1	1	/	1	/		✓ ✓	/	✓ ✓		
Safety Recall FOP LSC FON	2007 MY Highlander Hybrid Engineer Software Update for Air Fuel (A/F) Sensor Monitoring			✓ ✓	·	·	<i>'</i>	✓ ✓				V	✓	·		
LSC FOM	2014 MY Corolla Eco (2ZR-FAE) ECM Software Update for Variable Valve Lift Control 2011 MY Sienna 3rd Row Seat Back Panel Replacement			· /	·	·	·	~				·	· /	·		
Safety Recall FOL	2004-2005 MY RAV4 Front Driver Airbag Inflator Module						~	~	~	~	~	✓	~	√	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall FOK	2015 MY Scion tC Vehicles Rear Suspension Arm					✓				✓			✓	~		
Safety Recall FOJ	2014-2015 Model Year RAV4, 2015 Highlander and Highlander HV, and 2015 Camry and Camry HV Vehicles					✓				✓			✓	√		
Safety Recall FOI	2012 - 2014 MY RAV4 Electric (EV) EV Traction Motor Assembly											✓	✓	✓	012D	
Safety Recall F0H	2012 - 2015 MY Yaris Hatchback Headliner Replacement			✓	✓	✓	✓	✓				✓	✓	✓		
Safety Recall FOG	TRD Accessory Wheels and Light Truck Tires Tire and Loading Information Label			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall F0F	2015 Model Year Yaris Rear Axle Hub Bearing Torque Confirmation					✓				<			✓	✓		
Safety Recall F0E	Certain 2014 Model Year FJ Cruiser Vehicles					√				√			✓	✓		
Safety Recall FOD	Steering Intermediate Shaft Assembly Certain 2011-2012 Model Year Avalon Vehicles	 	-			\vdash	/	-	\dashv	+	1	\dashv	·	·		
Salety Recall FOD	Premium Audio System - Rear Sub-Woofer	ļ				$\sqcup \!\!\! \perp$							•			1
Safety (Noncompliance) Recall FOC	Certain 2014 and Early 2015 Model Year Prius V Vehicles Occupant Classification System (OCS) Sensor							✓	~	✓	✓	✓	✓	✓		
LSC FOB	Certain 2012-2014 Model Year Tundra and Sequoia Vehicles	1				\vdash	\dashv	-t	-t	\dashv	/	\dashv	✓	✓		
LSC FOA	Certain 2012-2014 Model Year Tundra and Sequoia Vehicles ECM Software Update			✓	~	✓	✓	✓	✓	✓	·	✓	·	·		
Safety Recall E07	Certain 2015 MY Sienna Vehicles Second Row Overhead Assist Grips							✓	✓	✓	✓	✓	✓	✓		
Safety Recall E05	Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles					1				/			~	/		
Surery Access Cos	Driver Side Front Suspension Lower Arm	1				\vdash	+	_							-	
Safety Recall E04 – High Absolute Humidity							~	~	✓	~	✓	✓	✓	✓	SC18A	All technicians that have already taken SC13B do not have to take SC18A
LSC E03	Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall E02	Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement					~				<			✓	✓		Remedy launched for vehicles in Boston, New York, CAT, Cincinnati, Denver, Portland and Chicago regions.
Safety Recall E01	Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak			✓	✓	✓	✓					✓	~	✓		
Safety Recall EOZ	Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag			<u> </u>		\vdash		✓	_		✓	✓	✓	V		1
Safety (Noncompliance) Recall EOY	Certain 2014 MY FJ Cruiser Trail Teams Ultimate Edition Package Lower Ball Joint Bolt	1	l	/	_	√ √	/	1		√	/	1	4	1	 	
Safety (Noncompliance) Recall EOX	Certain 2008-2014 MY Tacoma and FJ Cruiser TRD Accessory Wheels and Toyota Recommended LT Tires Certain 2014 Model Year Sienna Vehicles	1	l				h	- 1	_	_			√	✓	 	†
Safety (Noncompliance) Recall EOW	Transmission Shift Control Cable			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
LSC EOU	2007-2011 MY Camry Hybrid Vehicles Brake Reservoir Tank Replacement					\vdash			$\neg \dagger$	√	- t	_	~	~		
Safety Recall EOT	Certain 2014 Model Year Highlander and Highlander HV Passenger Seatbelt Selectable Force Limiter – Software Update							✓	✓	✓	✓	✓	✓	~		
Special Service Campaign ESS	Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable			✓	✓	✓	/	✓	~	✓	✓	✓	~	✓	l =	

i i						Ce	ertificat	tion Le	evel Re	eauirer	ments				-		
				Т	Con	tified		T		Expe			Т		+		
Safety Recall or Service Campaign	Description	Required Courses	Maint	-	CCI	linea	Т		Т	LAPCI		_	M	1ast MI	nΤ	Special	Additional Requirements
			ividiiic	EG	DT	СН	EL	EG	DT	CH	EL	. HY		idat	"	Courses	
Safety Recall EOS	Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable			✓	✓	✓			✓					< ×	_		
Safety Recall EOR	2014 Model Year Highlander Vehicles			1	/	1	/	/	1	/	_	· /	,	/ /	,		
,	2nd Row Passenger-Side Inboard Seat Track for 60/40 Split Seat																
LSC EOP	Certain 2014 Model Year Toyota Highlander Hybrid Vehicles Coolant Hose Clearance			<u> </u>								✓	٧	✓ ✓	_		
LSC EON	Certain 2011-2014 Model Year Toyota Sienna						1				/			/ /	/		
	Pre-Collision System (PCS) Driving Support ECU									_			_	,	,		
	09-10 Corolla, 09-10 Matrix, 08-10 Highlander, 09-10 Tacoma, 06-10 Rav4, 06-10 Yaris; Spiral Cable			-			1		_		· /			√ √ √ √			
Safety Recall EOL	06-10 Yaris HB, 07-10 Yaris Sedan, and 08-10 Scion xD; Driver's Seat Track Assembly & Passenger Track Assembly (3-Door Yaris Only)			/	V	· ·	· ·	٧		٧	٧	· ·		✓ ✓ ✓ ✓			
LSC EOK	2014 MY Avalon, Avalon Hybrid, Highlander, and Sienna Vehicles Safety Connect System Disabled			✓ ✓	✓ ✓	✓	· /	· /	✓ ✓	· /	<u> </u>	· ·		· ·			
LSC EOJ	Certain 2013-2014 Model Year Avalon & Avalon HV Driver & Passenger Front Seatback Board			· /	·	· /	· /	· ·	· /	· ·	<u> </u>	· ·		v v			
	2013 MY Highlander 2nd Row Left Hand Seat Inboard Seat Track 2003-2004 Avalon Supplemental Restraint System (SRS) Electronic Control Module			·	٧		· ·	٠	·	٧	· ·	·		· ·			
	2012-2013 MY Tacoma, 2012 RAV4 Brake Actuator Reprogramming			1		-	+	1	_	./	-	- /		· ·			
Safety Recall E0F	2012-2013 MY Tacoma, 2012 KAV4 Brake Actuator Reprogramming 2010-2014 Prius						+	· ·	· ·	· ·	•	· ·	_		_		
Safety Recall EOE	Software Update for Motor Generator ECU & Power Management ECU											✓		< V	′		
Safety (Non-Compliance) Recall EOC	2014 MY Highlander; 3rd Row Center Seat Belt			/	~	/	1	✓	✓	_	_	-	٠.	· ·	,		
	2014 with ringmanuler, 3rd wow Center Seat Bett Multiple 2013-2014 MY Models Seat Heater Assemblies			 	'	<u> </u>	-	+ ·	+-	÷	-	+ -		· ·			
Salety (Non-Compliance) Necali Eob	Multiple 2013-2014 Wit Models Seat Heater Assemblies			1		1	÷				÷		+-	` 			
Safety Recall DSF	03-04 MY Corolla, Matrix, & Tundra and 02-Early 04 MY Sequoia						1	✓	~	~	~	· /		✓ ✓	,	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall DSB	2003-2004 Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM) Front Passenger Airbag Inflator Module										~			· ·	,		* Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall DOU	2013-2014 MY Tacoma 4 Cylinder Valve Spring Replacement							✓	✓				*	✓ ✓			
Safety Recall D0T	2012-2013 Avalon, Camry, Camry HV, and Venza, 2013 Avalon HV HVAC Assembly										✓			✓			
Safety Recall DOS	2013 Avalon & Avalon HV, 2013-2014 Camry & Camry HV, 2014 Corolla Windshield Wiper Switch						✓				✓			✓			
Safety Recall DOR	2004-2005 and 2007-2009 Sienna Shift Lock Solenoid Assembly			✓	✓	✓	✓	✓	✓	✓	✓	· /	٧	✓ ✓	′		
LSC DON	2011-2012 HV Highlander HV Rear Driveshaft Assembly Replacement								√ **			✓	*	< ·	/	071	**Drivetrain Expert and completion of course 071 Toyota Hybrid System
Safety Recall DOM	2006-2010 MY Highlander HV Intelligent Power Module (IPM) Replacement											✓		✓			
Safety Recall DOL	2005-2011 MY Tacoma Access Cab Vehicles Driver and Front Passenger Seat Belt Assemblies						✓				✓		•	✓	_		
	2012 Yaris MY Power Steering Control Module						✓				✓		•				
Safety Recall D0H	Safety Recall D0H: 2010 Prius; Brake Booster Pump Assembly (Accumulator)					✓				✓			٧	✓ ✓	′		
Safety (Non-Compliance) Recall DOG	2007-2013 FJ Cruiser Genuine Toyota Auxiliary Light Kit Accessory																* Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
	2003-2004 Corolla, Matrix, Tundra and 2002-2004 Sequoia Front Passenger Airbag Inflator Module						~	~	~	~	~	· 🗸		·	,	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall DOC	2007 - 2013 MY FJ Cruiser Access Door Inner Panel			~	~	~	~	~	~	~	~	~		· ·	,		Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall D0B	2003-2004 MY Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM)										~		•	· ·	,		* Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall COM	Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007-2009 Camry, 2007-2009 Camry HV, 2008-2009 Scion xD, 2008-2009 x8, 2008-2009 Sequoia, 2008 Highlander and Highlander HV, 2009 Corolla, and 2009 Matrix Vehicles Power Window Master Switch (PWMS)			~	1	~	~	~	~	1	~	1		· •		SCC0M2	
	Multiple Models and Model Years 2GR-FE (V6) Engine VVTi Oil Hose			✓	<u> </u>	<u> </u>		✓						✓ ✓			
Warranty Enhancement Program ZF5	Certain 2012 – 2014 Model Year Prius V Extension of Warranty Coverage to the Intelligent Power Module (IPM)				<u> </u>	<u> </u>	<u> </u>		1		4_	✓		✓ ✓	_		
Warranty Enhancement Program ZF3	Certain 2010-2012 Prius, 2012 Prius V, 2010-2012 Prius Plug-In			/			1	1			1			/ /	<i>,</i>		
.,	Sticking Exhaust Gas Recirculation (EGR) Valve				 	 	+	-	1	-	+		_				
Warranty Enhancement Program ZE3	Certain 2010 – 2014 Model Year Prius Vehicles						1				1	✓		< V	·		
	Extension of Warranty Coverage to the Intelligent Power Module (IPM)			1	l	l	1	1	1	1					ı		