

<b>Document Title:</b>	Repair of the Murphy Bed Latch		
<b>Document Type:</b>	Technical Service Bulletin	<b>Make and Model:</b>	Ember Overland and Touring Series
<b>Document #:</b>	23-02	<b>Model Year:</b>	2022 and 2023
<b>Revision Date:</b>	August 8, 2023	<b>Flat Rate:</b>	Code: 50000190 0.5 Hours

<b>Material List</b>		
<b>Item Index</b>	<b>Ember Part Number</b>	<b>Description/Material Type</b>
1	95000415	METAL STRIKE PLATE MURPHY LATCH 1/4" THICK

## I. Purpose

To provide instructions on how to repair the murphy bed latch when identified to not latch securely on the Overland and Touring edition travel trailers.

## II. Procedure

1. Remove the silver strike plate for the murphy bed latch.



2. Place item 95000415, METAL STRIKE PLATE MURPHY LATCH 1/4" THICK behind the silver strike plate and secure as shown below:



3. Verify murphy bed latches securely.

### **Maintenance Recommendations/Other**

Safety, education, and customer satisfaction are our primary concerns. Should you have any questions, please contact us at 844-732-4204 or by email at [warranty@emberrv.com](mailto:warranty@emberrv.com).