

# 02-174: W990 Air Intake Covers

8/23/2023

[Edit](#) [Clone](#)

02-174

W990 Air Intake Covers

## Subject

W990 Air Intake Covers

## Whats New Abstract

### Fix-As-Fail

Certain W990 hood-mounted engine air intake covers could loosen and rattle or separate from vehicle. New air intake covers are available with improved retention. Installation of new covers requires hood modification. Procedures are available for replacement of hood-mounted engine air intake covers.

## Condition

Certain engine air intake covers on W990 chassis could loosen and rattle or separate from vehicle. Updated covers are available to provide better retention. Installation of improved covers requires hood modification. See attached procedures for modification instructions.

## Chassis Affected

Any W990 chassis built before 01/16/2023.

## Action

### Fix-As-Fail

If a customer comes into your dealership and demonstrates the condition above, follow the procedures to replace air intake covers and modify the hood.

## Warranty

Kenworth will pay for parts at dealer net plus applicable mark-up and labor up to 3 yrs / 500,000 miles

(805,000 km) :

- **1.6 hours** labor to replace Air Intake covers and modify hood. Use Quick Claim Code **02174**.
- File an additional claim for extraordinary circumstances. A quick claim for standard labor must be filed first.
- File the claim within 14 days in accordance with Warranty Policy [CA009](#).

<b>PRWS CLAIM CODING</b>			
Campaign Code:	02174	Campaign Type	Field Repair
Claim Category:	Truck	Repair Type	Fix-As-Fail
Customer Concern Code	062	Causal Code	19
Corrective Action Code	03	Responsibility Code:	Camp
Failure Location	002-004-085	Causal Part	L22-1146 AND L22-1146R
Supplier Code	N/A	SRT Code	<b>B23-09A</b> <b>1.6 hrs</b> Replace air intake covers and modify hood per bulletin procedures.

## Parts

---

Parts are available from PACCAR Parts.

Quantity	Part Number	Description
1	L22-1196	Air Intake Cover, Left Side
1	L22-1196R	Air Intake Cover, Right Side
As Needed	Source Locally	Masking Tape
As Needed	Source Locally	Paint Safe Cleaning Solvent (3M Citrus Base Cleaner or equivalent)

## Procedure

---

**Please follow your dealership's safety procedures and precautions to ensure the vehicle can be safely repaired and maintained. Read all steps before beginning.**

Follow steps in attached [Procedures Document](#).

## Attachments

---

[W900 Hood Templates](#)

[Procedures](#)

---

Authored by: JB3