

SSM 51850 2021-2022 Bronco - Soft Top Roof - Loose Exterior Fabric On Rear Window

Some 2021-2022 Bronco vehicles equipped with a soft top roof may exhibit loose exterior fabric on the rear window assembly. This may be due to broken D-pillar clips on the rear window. To correct the condition, replace the rear window. Refer to the Workshop Manual (WSM), Section 501-18A > Removal and Installation > Soft Top Assembly.