



Technical Journal Title PAC-U230051 after software update		Ref. No. TJ 36629.1.0	
Issuer (Dept.) Technical Service		Issue Date 06/14/23	Status Date 06/27/23
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3870	
Function Description Driver support systems		Page Page 1 of 2	

DESCRIPTION:

If DTC PAC-U230051 is stored in the car immediately following a Software Update, please follow the advice listed under Service.

The DTC could occur directly after downloading new software to the car, usually during the Pre-delivery service.

The parking camera is fully functioning with this DTC, and there are no symptoms to the driver.

PAC: Parking Assistance Camera

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use

DTC Diagnostic Trouble Codes

ECU	DTC	Fault Type
PAC	U230051	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-9999		0000001-9999999	201835-999952
225							2019-9999		0000001-9999999	201817-999952
227							2019-9999		0000001-9999999	201846-999952
234							2017-9999		0000001-9999999	201617-999952
235							2017-9999		0000001-9999999	201620-999952
236							2017-9999		0000001-9999999	201646-999952
238							2017-9999		0000001-9999999	201646-999952
246							2018-9999		0000001-9999999	201717-999952
256							2016-9999		0000001-9999999	201505-999952
536							2018-9999		0000001-9999999	201746-999952
539							2022-9999		0000001-9999999	202140-999952

SERVICE:

Do NOT replace any hardware in the car!

There is no need to fault trace the car due to this DTC.

This DTC should be considered a ghost code and can be ignored.

Warranty claim info:

No warranty claim is accepted.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3870.