

**Volvo Car USA LLC****Parts Bulletin**

Bulletin Title	Group	CAT/NO
Service Action A10241 BECM Update Model Year 2022-2023 S60, V60, S90L, XC60 and XC90	31	A10241
Car Market	Issue Date	Status Date
United States and Canada	7/7/23	7/7/23
Revisions	Page	
	Page 1 of 1	

Reference Bulletins: QB A10241

Volvo Car USA LLC and Volvo Car Canada LTD on behalf of Volvo Car Corporation, has decided to launch Active Service Action A10241 on certain Model Year 2022-2023 S60, V60, S90L, XC60 and XC90 vehicles.

Volvo Cars quality investigations have identified that the Battery Energy Control Module (BECM) monitoring state is too sensitive and may cause the Malfunction Indication Light (MIL) to illuminate inaccurately.

The corrective action is to perform a Total Software Upgrade. A10241 affects 25,774 vehicles in the U.S. and 1,783 in Canada.

The following part numbers apply:

Part Number	Description	Qty
31483292	Total Upgrade XC60, XC90	1
31472405	Total Upgrade S90L	1
31493704	Total Upgrade S60, V60	1