

Technical Service Bulletin

SUBJECT:

CHANGE TO SPLASH SHIELD REMOVAL/INSTALLATION – SERVICE MANUAL REVISION

No: TSB-23-42A-003

DATE: August 2023

MODEL: Outlander Sport

 CIRCULATE TO:
 [] GENERAL MANAGER
 [X] PARTS MANAGER
 [X] TECHNICIAN

 [X] SERVICE ADVISOR
 [X] SERVICE MANAGER
 [X] WARRANTY PROCESSOR
 [] SALES MANAGER

PURPOSE

This TSB provides a change to the number of clips (reduced from 14 to 12) for the Splash Shield Removal and Installation section of the applicable Service Manual.

	Previous		New
Application timing of production	Up to early January 2023		From Middle January 2023
Repair method (for Left/Right side)	Clip x 14pcs, Bolt (& Weld nut) x 1pc	\rightarrow	Clip x 12pcs, Bolt (& Weld nut) x 2pcs, Spring nut & Bolt x 1pc

AFFECTED VEHICLES

2023 Outlander Sport

AFFECTED SERVICE MANUAL

• 2023 Outlander Sport Service Manual

PROCEDURE

Please use the following chart as a guide to replace the indicated page in the affected Service Manual, Group 42, Body, Splash Shield.

Applicable manual	Pub. No.	Applicable title	Content
2023	MSCD-017B-2 023	BODY	Attached
OUTLANDER SPORT		└SPLASH SHIELD	Sheet 1
Service Manual		ddash REMOVAL AND INSTALLATION	



Copyright 2023, Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com).

SPLASH SHIELD

REMOVAL AND INSTALLATION

<Changed> M14210097A0056

