

Technical Service Bulletin

SUBJECT:			NO:	TSB-23-34-002
REAR SHOCK ABSORBER REMOVAL AND			DATE:	August 2023
INSTALLATIO	N – SERVICE MANU	AL REVISION	MODE	: See below
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X]TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[] SALES MANAGER		[] SALES MANAGER

PURPOSE

This TSB provides the addition and correction to the removal and installation of the Rear Shock Absorber in the applicable Service Manual sections:

Suspension

AFFECTED VEHICLES

2022 - 2024 Outlander 2023 - 2024 Outlander Plug-in Hybrid

AFFECTED SERVICE MANUAL

- 2022 2024 Outlander Service Manual
- 2023 2024 Outlander Plug-in Hybrid Service Manual

PROCEDURE

Please use the following chart as a guide to replace the indicated pages in the affected Service Manuals, Group 34, Suspension, Rear Suspension, Removal and Installation, Rear Shock Absorber, Exploded View.

Applicable Manual	Pub. No.	Applicable Title	Contents
2022	MSCD-030B-2022	SUSPENSION	Attached
OUTLANDER	(Volume 3)	└ REAR SUSPENSION	sheet 3
Service Manual		dash REMOVAL AND INSTALLATION	
2023	MSCD-030B-2023	└ REAR SHOCK ABSORBER	
OUTLANDER	(Volume 2)	└ Exploded View	
Service Manual			
2024	MSCD-030B-2024		
OUTLANDER	(Volume 2)		
Service Manual			
2023	<mmna></mmna>		Attached
OUTLANDER (PHEV)	MSCD-027B-2023		sheet 2
Service Manual			
2024	<mmna></mmna>		
OUTLANDER (PHEV)	MSCD-027B-2024		
Service Manual			




Copyright 2023, Mitsubishi Motors North America, Inc.

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com).

8/17/2023 1 of 3 (5348/MSB23M34001)

REMOVAL AND INSTALLATION REAR SHOCK ABSORBER


Exploded View



8/17/2023 2 of 3 (5348/MSB23M34001)

REMOVAL AND INSTALLATION REAR SHOCK ABSORBER

Exploded View



8/17/2023 3 of 3 (5348/MSB23M34001)