

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Electrical

Topic: Odometer discrepancies after swapping control module

Condition: N/A

Diagnostic Trouble Codes: B12A286

Measure

It has been identified that by swapping the ICU (infotainment control unit) on Artura vehicles from one to another it may cause odometer discrepancies and result in the Instrument Cluster reading "-----".

Under no circumstances should the ICU be swapped from Artura vehicles to prevent potentially causing incorrect odometer values to be stored unless specifically instructed to by the Technical Support team.

Parts Information

16MB583CP - Infotainment ECU

Attachments

N/A

KA Update Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.