FRONT INTERIOR COURTESY LIGHT - NON-ILLUMINATION

Customer Voice:

Interior courtesy lights are not automatically illuminating

Technical Description:

JLR Engineering investigations have found reports of customers unintentionally deactivating the front interior courtesy lights, causing it not to automatically illuminate.

Status:

The automatic interior light illumination can be deactivated/reactivated by touching the front interior light lens for five seconds. Reactivation & Deactivation are confirmed by either the interior light flashing and/or a message on the instrument cluster.

If the customer issue is resolved by reactivating the auto illumination function, refer the customer to the relevant section within the 'iGuide online', for future reference.

If the reactivation of the interior light illumination does not resolve the customer issue, then refer to the diagnosis and testing in TOPIx, ('417-02: Interior Lighting' > 'Diagnosis and Testing' > 'Interior Lighting').

Range Rover

- 22-23MY New Range Rover
- 23MY New Range Rover Sport
- 21-23MY Evoque
- 21-23MY Velar

Defender

20–23MY Defender

Discovery

- 21-23MY Discovery
- 21-23MY Discovery Sport

Jaguar

- 21-23MY I-PACE
- 21-23MY F-PACE
- 21-23MY XF
- 21-23MY E-PACE



SSM 76047 / SSM 76048 available on TOPIx