

## FRONT OVERHEAD CONSOLE RATTLE

### Customer Voice:

- That there is a rattle or creak type noise emanating from the front overhead console area.

### Technical Description:

- This may be caused by contact between the console cover and the covered components.

### Status:

- **SSM 76053** has been published to address this concern, providing repair guidance.

### Range Rover

- 22-23MY Range Rover
- 23MY RR Sport

