

## INTERIOR TRIM DAMAGE NOTED AT PDI

### Customer Voice:

- Retailers may report that there is damage to interior trim pieces, found before or during PDI.

### Technical Description:

- Engineering is investigating claims for interior trim damage found on or before PDI.

### Status:

- To support this investigation, engineering requests an EPQR be submitted with pictures of the damage.
- **SSM 76012** has been published to address this concern.

### Range Rover

- 23MY Range Rover
- 23MY RR Sport

