

Reference	SSM76054
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Charging Port Locking Pin Not Engaging Or Disengaging
Category	Electrical
Last modified	08-Aug-2023 00:00:00
Symptom	205000 Electrical Accessories

Content**Model / Model Year / Derivative**

Range Rover (L460) / 22MY onwards / Plug-in Hybrid Electric Vehicle (PHEV)
Range Rover Sport (L461) / 23MY onwards / PHEV

Situation:

JLR Engineering investigations have found that in some cases the charge cable does not lock into the charge port. As a result, the vehicle is not charging.

Cause:

The PHEV charging port emergency release cable has been misrouted during production.

Action:

Follow the instruction(s) below.

SERVICE INSTRUCTION:

Refer to TOPIx Workshop Manual section 612-02: Power Distribution And Charging System - Removal and Installation - Charging Socket Emergency Release Cable. Make sure the PHEV charging port emergency release cable is routed correctly.

(Ref 000363882)

anBhdHRicnM7MjAyMy0wOS0wOFQxMzo1NjpoOC4wNTIaOzEzNi4yMjYyNzQzMTEzOw==