



# Service Bulletin

Bulletin No.: 23-NA-139

Date: August, 2023

## INFORMATION

**Subject:** Information on Internal Transmission Faults Related to Components Not Serviceable at Dealer Level, Service Transmission Message Displayed on Driver Information Center (DIC), Malfunction Indicator Lamp (MIL) Illuminated – DTC P1955 and/or P0867 Set

This service bulletin replaces PIP5797E. Please discard PIP5797E.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2023	—	—	All	All

<b>Involved Region or Country</b>	North America, Europe, Middle East, Australia/New Zealand
<b>Condition</b>	Some customers may comment on one or more of the following: <ul style="list-style-type: none"> <li>MIL illuminated.</li> <li>Service Transmission Message displayed on the DIC.</li> </ul> Technicians may find one or more of the following DTCs set in the transmission Control Module (TCM): <ul style="list-style-type: none"> <li>P1955</li> <li>P0867</li> </ul>
<b>Cause</b>	Internal transmission faults related to components not serviceable at the dealer level.
<b>Correction</b>	If DTCs P1955 or P0867 are current or in history, the transmission assembly will require replacement. Do not attempt any other repairs for these DTCs other than transmission assembly replacement following service information and labor times. <p><b>Note:</b> Please do not drain the transmission prior to replacement. Engineering would like to get the transmission back with original fluid still in unit.</p> <p><b>Note:</b> An MCV replacement will not repair vehicles with P0867 or P1955 current or in history.</p>

**Important:** Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

## Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8486338*	Perform Diagnostics and Reset Codes P1955 and/or P0867	0.2 hr
*This is a unique Labor Operation for bulletin use only.		

Version	1
Modified	Released August 09, 2023

