



SIB 63 09 23
REAR INTERIOR LIGHTS ARE INOPERATIVE

2023-08-14

THIS REPAIR IS MOBILE FRIENDLY

MODEL

E-Series	Model Description	Production Date	Affected Option Code
F95 (X5 M Sports Activity Vehicle)	F96 (X6 M Sports Activity Coupe)	G05 (X5 Sports Activity Vehicle)	G06 (X6 Sports Activity Coupe)
G07 (X7 Sports Activity Vehicle)	G09 (BMW XM SAV)		

SITUATION

The interior lights in the rear of the passenger area do not work.

G05, G06, and G07 second row interior light



G07 third row interior light





G09 second row interior light

CAUSE

Unfavorable actuation of the interior light.

CORRECTION

Perform a 10-minute battery reset.

PROCEDURE

When a Model vehicle listed above arrives with the issue described in the Situation section, proceed first as follows:

1. Perform a 10-minute battery reset following the repair instructions listed in ISTA/AIR (61 20 900) and check the functionality of the interior lights.
2. If the interior light does not work after the battery reset, continue with your diagnosis.

PARTS INFORMATION

Note: Parts replacements do not provide a solution!

CLAIM INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Repair Code:	6331001200	Interior light Permanent failure
---------------------	-------------------	---

Obtain the flat rate unit (FRU) allowances for the following that applies.

Labor Operation	Description	Labor Allowance
61 20 900	Disconnecting and connecting battery ground lead	As applicable

And, if applicable to a Model vehicle listed above and to the repair being performed:

Labor Operation	Description	Labor Allowance
61 20 910	Additional work disconnecting and connecting negative battery cable 12-V lithium-ion auxiliary battery	As applicable

Other Repairs

If other eligible and covered work is performed because of performing the ISTA diagnostics, the related test plans, and/or other diagnosis, claim this work with the applicable Repair Code and the labor operation codes (including the diagnosis) that applies.

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group' AIR application resource, start by entering the Chassis Number, which consists of the VIN's last seven (7) characters or use the full VIN. Click on the "Search" button, and then enter the applicable flat rate labor operation in the FR code field.

*Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

