

SERVICE BULLETIN 607 - BATTERY FUSE REPLACEMENT



Notice Information

Ref	24640
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – July 5, 2023

TOL Ref. #24640- SVC

SERVICE BULLETIN 607 – BATTERY FUSE REPLACEMENT

Dealers are requested to install a replacement battery fuse and attach a new fuse box label as outlined in Service Bulletin 607, [attached](#) to this TOL.

Customer Contact Instructions

Motorcycles in the affected VIN range must be modified prior to delivery to the customer, or at the next visit to the dealership.

Identification of Affected Motorcycles

Rocket 3 GT, Rocket 3 R, Rocket 3 TFC, Rocket 3 R Black and Rocket 3 GT Triple Black motorcycles in the below VIN range.

Bulletin Number	Models Affected	VIN Range	Markets Affected
607	Rocket 3 GT Rocket 3 R Rocket 3 TFC Rocket 3 R Black Rocket 3 GT Triple Black	Up to BL6215	All Markets

Reminder: use the '[VIN Enquiry](#)' function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

-

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact your Triumph Regional Manager or Triumph Customer Support at (888) 284-6288.