

TDT 2023-03 AND TDT 2023-04 BUG NOTIFICATION

TRIUMPH

Notice Information

Ref

24856

Posted Date:

Posted To:

General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive

Subject:

Service/Technical

TOL NOTICE (US&CA) – August 4, 2023

TOL Ref. #24856- SVC

TDT 2023-03 AND TDT 2023-04 BUG NOTIFICATION

Please read below concerning a system bug notification present on TDT 2023-03 and TDT 2023-04.

Description of the Bug:

A “Rear Position Light Fault” error message can falsely be displayed on the instruments of New Tiger 1200 models (PM1, PR1, PS1, PX1, PY1) using either the TDT 2023-03 or TDT 2023-04 CCU calibration.

We can confirm that this is an **incorrect** warning message and that the function of the rear light is unaffected. A revised CCU calibration is being developed and will be released with a new TDT update ASAP.

To lessen the impact to customers, we advise dealers **do not** download the latest CCU calibration from TDT 2023-03 or TDT 2023-04 to New Tiger 1200 models (PM1, PR1, PS1, PX1, PY1) until further notice.



Thank you and if you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.