| : | NNTIS SERVICES | | ical Service Bulle | ` ' | |
|-----------------------|--|-------------|--------------------|--------------------------------|---|
| REFERENCE: | TSB : 08-161-23 GROUP 08 - Electrical | Date: | July 7, 2023 | REVISION: | - |
| VEHICLES AFFECTED: | 2023 (WS) Grand Wagoneer/Wagoneer This bulletin applies to vehicles built on and after January 17, 2023 (MDH 0117XX) and on and before March 29, 2023 (MDH 0329XX) equipped with Rear Seat Video Group (Sales Code AV1) and Seatback Video Screens (Sales Code RHH). | | □NA | PPLICABILITY: ☐ CH ☐ IAP ☑MEA | |
| CUSTOMER SYMPTOM: | The vehicle is missing the second m | edia remote | . | | |
| CALISE: | The second media remote is missing | ı | | | |

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-202, date of issue July 07, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/ Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

REPAIR SUMMARY:

This bulletin involves placing the missing media remote in the vehicle, and informing customer that the second remote is in the vehicle.

CLAIMS DATA:

| Labor Operation No: | Labor Description | Skill Category | Labor Time |
|---------------------|---|------------------------------------|------------|
| 08-20-03-91 | Second Remote - Place In Vehicle (0 - Introduction) | 6 - Electrical and Body Systems | 0.1 Hrs. |
| Failure Code | ZZ | Service Action | |

SPARE PARTS:

| Qty | Part No. | Description | Notes |
|-----|------------|--------------|-------|
| 1 | 68596059AA | Media Remote | |

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

08-161-23 -2-

REPAIR PROCEDURE:

1. Add one media remote to the vehicle (Fig. 1) .



Fig. 1 Media Remote

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.