

## **Technical Service Bulletin (TSB)**

# Radio Over The Air Updating to QR40.12 Software Version

REFERENCE:	<b>TSB</b> : 08-181-23 <b>GROUP</b> 08 - Electrical	Date:	July 26, 2023	REVISION:	_
VEHICLES AFFECTED:				MARKET AF	PPLICABILITY:    MEA   IAP   CH
CUSTOMER SYMPTOM:	<ul> <li>Mobile Wi-Fi inoperative upon start up.</li> <li>Hotspot gives "No Internet" connection message on phone, when trying to connect to a device.</li> </ul>				
CAUSE:	Radio Software				

#### **REPAIR SUMMARY:**

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from QR39.62 and QR39.57 to QR40.12.

NOTE: National launch for this FOTA update is expected to begin August 16, 2023.

08-181-23 -2-

#### **DISCUSSION:**

Vehicles sold in the U.S. and Canada can now receive software updates "over-the-air". Updates to software will occur in a phased roll-out. The software is updated through the built-in cellular modem in the radio.

Customers will see a notification on their radio screen when new software is available for their radio (Fig. 1). The owner will have the option to update the radio or schedule the update for later. There is not an option to decline the update indefinitely, the update must be performed.



Fig. 1
Software Acceptance Screen

NOTE: If selecting "Schedule Update" the screen below will be displayed. The customer can select the exact time they want the update to begin (Fig. 2).



Fig. 2 Schedule Update Screen

1. The vehicles transmission needs to be in the "Park" position, or have the vehicle in "Neutral" with parking brake engaged if equipped with a manual transmission. The ignition needs to be in the off position.

2. Whether the customer selects "Update Now", or "Schedule Update" (Fig. 1) and sets a time, they can shut off the vehicle and leave. The update will be completed automatically (Fig. 3).

NOTE: This step may take several minutes to complete.




Fig. 3
Update In Progress Screen

3. Upon completion of update, the radio will display a confirmation message (Fig. 4).



Fig. 4
Update Confirmation Screen

### POLICY: Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.