

# Technical Service Bulletin (TSB)

Third Row Sunshade Tab Stuck Between Door Panel

REFERENCE:	TSB: 23-085-23 GROUP 23 - Body	Date:	July 27, 2023	<b>REVISION</b> :	-
VEHICLES AFFECTED:	2023 (RU) Chrysler Pacifica This bulletin applies to vehicles built or 0517XX) and on or before May 18, 2023 2ND & 3RD Row Window Shades (Sales	6 (MDH 0518XX) equipped with		MARKET AP ⊠NA ⊡SA ⊡EE	PLICABILITY: MEA IAP CH
CUSTOMER SYMPTOM: CAUSE:	Customers may comment on the follow • The third row window shade is stu Incorrect installation of the interior pan	ck.			

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-224, date of issue July 27, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/ Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

#### **REPAIR SUMMARY:**

This bulletin includes Inspecting and if necessary getting the window shade tab unstuck from the interior panel.

## CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
23-10-56-95	Window Shade Tab – Inspect and/or Repair (One or Both Sides) (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure code	ZZ	Service Action	

#### **DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

23-085-23

## **REPAIR PROCEDURE:**

1. Verify the third row sunshade tab is not stuck between the trim panel on both the left side and right sides (Fig. 1).



Fig. 1 Sunshade Tab

- 1 Stuck Tab
- 2 OK
- 2. If the tab is stuck between the trim panel, use a trim stick to pry the sunshade tab out (Fig. 2).



Fig. 2 Trim Stick To Remove Stuck Tab

3. Verify the third row sunshade operates properly.

## **POLICY:**

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.