

REFERENCE:	Nova Bus Manuals
SECTION:	17: Radios and accessories
RS N°:	MQR 7621-2237
EFFECTIVE IN PROD.:	NA

APPLICATION DEADLINE:2024OC23  
CLAIM REFERENCE NUMBER: WB-5463

SUBJECT:	Front camera bracket breaking.
JUSTIFICATION:	Failure of camera bracket will cause the camera to swing while bus is in motion.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Install the new design bracket whole assembly.	Nova Bus	Nova Bus	1 h
2	–	–	–	–

#### MATERIAL REQUIRED PER VEHICLE

QTY	PART N°	REV.	DESCRIPTION
<b>LEVEL 1</b>			
1	N108657	–	Bracket Forward Facing Camera
4	N16729	X	Screw M6X35 R/C CR B633 Type VI
4	N44689	A	Washer Lockheli M6 SSA4
4	N17565	X	Washer flat OVS M6 SS DIN9021
4	N16914	X	Rivnut M6 CYL YP OP GR0.5-3.0
<b>LEVEL 2</b>			
–	–	–	–
<b>SHOP SUPPLY</b>			
2 ml	N97665	A	Threadlocker loctite 243 (50 ml Bottle)

Materials will be available within 49 days once your order has been placed.

To order, please contact novabus.parts@volvo.com

Or by phone for CANADA 1-800-771-6682, for USA 1-877-999-8808

Specify document number, quantity of parts required and shipping address.

#### DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED *	RETAINED	* Dispose of the unused parts and the defective parts in accordance with local environmental standards in effect.
	Yes	–	

#### REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2023AU16	Initial release	Nandan B S

APPROVED BY:

Irina  
Signature  
numérique de  
Irina  
Negoescu

PAGE 1 OF 2

NQF772004 VERSION 3

Negoescu Date : 2023.08.31  
08:14:25 -04'00'

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
New York City Transit - NYCT	L958	5439	5442	S92J9G97755	S92J9G97756	4
New York City Transit - NYCT	L959	5443	5443	S92J0H97761	S92J0H97761	1
New York City Transit - NYCT	LA23	5485	5530	S92J5J97763	S92J6J97765	46
New York City Transit - NYCT	LB59	5444	5484	S92J7H97761	S92J6H97763	41