



## STAR ONLINE PUBLICATION



**Case Number:** S2323000060

**Release Date:** August 2023

**Symptom/Vehicle Issue:** Buzz Squeak Rattle (BSR) From 2<sup>nd</sup> Row Seat.

**Customer Complaint/Technician Observation:** Customer notices slight buzz or rattle from the 2nd row seat cushion. Noise could occur on rough roads or bumps.

**Discussion:** With the seat in place and assembled, inspect under the seat for clip and harness location. The seat cover J clip should be centered, and the wire harness should be properly fixed to the seat frame using the harness attached clips.



Examples of properly attached J clip (right) and harness (left)

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**