

STAR ONLINE PUBLICATION















Case Number: S2308000035 Rev. B

Release Date: August 2023

Symptom/Vehicle Issue: U1202-00 Lost Communication with Electric Vehicle Control Module Set Erroneously in The Radio (ETM)

Discussion: When scanning the vehicle for DTC's you may find an Active U1202-00 Lost Communication with Electric Vehicle Control Module in the Radio (ETM).

The 2.0L GME engine equipped in the Dodge Hornet does not have electrified powertrain components. The fault is setting erroneously and should be ignored. There are no customer concerns related to this DTC.

A Radio (ETM) software update to disable setting this fault is scheduled to be released in 2024.

Do Not Replace Any Components For This DTC

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

Stellantis US LLC Version 4.5 06/08/2022